

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012124/ETY3N2**Date:** 17/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00243322100

Claimant Vehicle No : SKX572J **Insured Vehicle No :** SJP7306U

Date of Loss: 24/11/2021 Nature of Claim: TP Claim No: SNM21D206821/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX572J**

Make & Model: MAZDA 3, 1.5 4 DOOR SEDAN SP (A) Engine No: P520329164

Reg. Date: 25/11/2015 (Man. Year: 2015) Chassis No: JM6BM42A8G0323899

Colour: White Odometer: 149660 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,449.60	3,936.00	513.60	11.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,670.00	650.00	28.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,769.60	5,606.00	1,163.60	17.19
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	6,769.60	4,500.00	2,269.60	33.53
+ GST 7.00/7.00% (S\$)	473.87	315.00	158.87	33.53
Nett Amount (S\$)	7,243.47	4,815.00	2,428.47	33.53

INSPECTION

Date of Assignment: 15/02/2022

Date Inspected: 30/11/2021 Inspected At: BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08
SINGAPORE 159722
REPAIRER: MOVA AUTOMOTIVE PTE LTD

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Feb 2022)
Parts:	143	MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX572J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,004.00 FL	*1,004.00 FL
2	1		*BOOT LID LOGO	Necessary	77.00 FL	*77.00 FL
3	1		*BOOTLID EMBLEM-MAZDA 3	Necessary	55.00 FL	*55.00 FL
4	1		*BOOTLID EMBLEM-SKYACTIVE	Necessary	66.00 FL	*66.00 FL
5	1		*BOOTLID LAMP LH	Cracked	275.00 FL	*275.00 FL
6	2		*BOOTLID HINGE LH & RH	Not Necessary	316.00 FL	*- FL
7	1		*BOOTLID LOCK	Bent	186.00 FL	*186.00 FL
8	1		*BOOTLID RUBBER	Crushed	135.00 FL	*135.00 FL
9	1		*TAILLAMP LH	Cracked	534.00 FL	*534.00 FL
10	1		*REAR BUMPER	Broken	1,127.00 FL	*1,047.00 FL
11	1		*REVERSE SENSOR LH	Broken	193.00 FL	*193.00 FL
12	1		*REAR BUMPER TOW COVER LH	Missing	28.00 FL	*28.00 FL
13	1		*REAR BUMPER REFLECTOR LH	Broken	55.00 FL	*55.00 FL
14	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
15	2		*REAR BUMPER SIDE RETAINER LH & RH	Broken	76.00 FL	*76.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	563.00 FL	*563.00 FL
17	1		*END PANEL TOP GARNISH	Broken	99.00 FL	*99.00 FL
18	1		*END PANEL	Dented	530.00 FL	*447.00 FL
19	1		*ANTENNA SENSOR	Not Necessary	143.00 FL	*- FL
20	1		*SPARE TYRE TOP BOARD (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*TOOL SPONGE LH (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
23	1		*REAR CHASSIS LH (NPA)	Repair	0.00 FL	*- FL
24	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
25	1		*TAILLAMP PANEL LH (NPA)	Repair	0.00 FL	*- FL
26	1		*REAR NUMBER PLATE	Cut	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,552.00	4,910.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,102.40	974.00
Total Parts (\$\$)	4,449.60	3,936.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO INSPECT REAR LIGHTING MECHANISM & CHECK WIRING	New	80.00	30.00
2	TO INSTALL REVERSE SENSOR & DIAGNOSE FUNCTION	New	80.00	30.00
3	TO CUT OFF END PANEL,TO KNOCK & STRAIGHTEN ON REAR FENDER LH,TAILLAMP PANEL LH,SPARE TYRE PANEL & CHASSIS MEMBER LH,TO REMOVE & REPLACE DAMAGED ITEMS,REALIGN CONNECTION	New	900.00	700.00
4	TO REMOVE & REFIT REAR COMPARTMENT & FITTING	New	80.00	50.00
5	TO APPLY BODY JOINT SEALANT ON CUTTING AREA	New	100.00	30.00
6	TO RUST PROOF ON REPAIR AREAS	New	100.00	30.00
7	TO REMOVE & ALIGN REAR EXHAUST MUFFLER	New	80.00	0.00
8	TO SPRAY PAINT ON REPAIRED AREAS	New	900.00	800.00
Gross Labour Cost (\$)			2,320.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >