

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012126/UTY3N2**Date:** 14/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00002532100

**Claimant Vehicle
No :** SJK9623S**Insured Vehicle
No :** SKF1013U

Date of Loss: 25/11/2021

Nature of Claim: TP

Claim
No: SNM21D206829/C03/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJK9623S**

Make & Model: NISSAN QASHQAI, 1.2 (A)

Engine No: HRA2584028A

Reg. Date: 26/03/2018 (Man. Year: 2018)

Chassis No: SJNFEAJ11U2215424

Colour: Brown

Odometer: 61042 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17

Rear Tyre Size: 215/60R17

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,829.74	2,212.30	2,617.44	54.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,680.00	600.00	26.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,109.74	3,892.30	3,217.44	45.25
+ GST 7.00/7.00% (\$\$)	497.68	272.46	225.22	45.25
Nett Amount (\$\$)	7,607.42	4,164.76	3,442.66	45.25

INSPECTION

Date of Assignment: 16/12/2021

Date Inspected: 02/12/2021

Inspected At:

Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,126.60 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2022)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK9623S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT RH SPRING RUBBER SEAT	Not Necessary	22.20 FN	*- FN
2	1	*FRT RH LOWER RUBBER SEAT SPRING	Not Necessary	33.00 FN	*- FN
3	1	*FRT RH SHOCK MOUNTING TOP	*Check	99.10 FN	*- FN
4	1	*FRT RH LOWER ARM	*Check	249.40 FN	*- FN
5	1	*FRT RH FENDER WHEEL ARC MOULDING	Distorted	540.50 FN	*540.50 FN
6	1	*FRT RH DOOR WINDOW OUTER MOULDING	Not Necessary	200.10 FN	*- FN
7	1	*FRT RH DOOR RR SASH TAPE	Not Necessary	32.40 FN	*- FN
8	1	*FRT RH DOOR RR INNER SASH TAPE	Not Necessary	16.30 FN	*- FN
9	1	*FRT RH DOOR TOP SASH TAPE	Not Necessary	106.60 FN	*- FN
10	1	*FRT RH FENDER	Dented	685.00 FN	*685.00 FN
11	1	*FRT RH DOOR	Repair	1,166.20 FN	*- FN
12	1	*FRT RH INSULATOR STOPPER SHOCK ABSORBER	Not Necessary	89.10 FS	*- FS
13	1	*FRT RH SHOCK ABSORBER TOP BOUND BUMPER RUBBER	Not Necessary	40.30 FS	*- FS
14	1	*FRT RH SHOCK ABSORBER	*Check	560.30 FS	*- FS
15	1	*FRT RH WHEELHUB	*Check	287.50 FS	*- FS
16	1	*WHEEL ALUMINIUM FRT RH	Cut	1,231.90 FS	*1,231.90 FS
17	1	*SUNDRIES	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	5,459.90	2,457.40
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	630.16	245.10
Total Parts (\$\$)	4,829.74	2,212.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR CHARGES TO RENEW FRT RH FENDER & FRT RH DOOR REMOVE AND INSTALL FRT BUMPER	New	1,120.00	700.00
2	CHARGES TO SPRAY PAINTING FRT RH FENDER & FRT RH DOOR	New	750.00	750.00
3	RENEW FRT RH WHEEL RIM AND BALANCING	New	15.00	15.00
4	PERFORM WHEEL ALIGNMENT	New	95.00	95.00
5	REMOVE AND TRANSFER FRT RH DOOR MECHANISM	New	80.00	0.00
6	APPLY SEALANT TO FRT RH DOOR	New	100.00	0.00
7	COMPUTER CHECK DIAGNOSIS (SYSTEM FAULT & TRACTIONCONTROL WARNING LIGHT ON)	New	120.00	120.00
Gross Labour Cost (S\$)			2,280.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >