

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	INSURANCE (S) PL	F	Ref:	CS/AGI21012127/Atf3n2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	[	Date:	25/01/2022	
			(	Code:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMG 8329J	Veh. Inspected		GBJ 2424X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10012655/KY	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		30/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA DYNA	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTFAT35Y70K212613	Colour		GREY	
	Odometer	59930 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	R/H Rear Tyre	155 R12C	DUNLOP		6 mm	
	L/H Rear Tyre	155 R12C	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	26/11/2021	Inspection Date		01/12/2021	
	Survey held at SM AUTOMOTIVE					
		BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: