

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	Ref		CS3/ASM21012131/Guy3e2	
	8 SHENTON WAY SINGAPORE 0688	Dat	e:	06/12/2021		
	ATTN: LOH CYNTH	HIA	Cod	de:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 4271C	Veh. Inspected		SMY 4141P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03N5A	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		30/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SHUTTLE 1.5G	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	GK82101964	Colour		GREY	
	Odometer	48903 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	185/60 R15	FIRENZA		6 mm	
	L/H Rear Tyre	185/60 R15	FIRENZA		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	AR PORTION.				
5. General Information						
	Accident Date	27/11/2021	Inspect Date / Time	е	01/12/2021 (05:30 PM)	
	Survey held at	eld at A-TEC AUTOMOTIVE PTE LTD				
		8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/ASM21012131/Guy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor