

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# XE1354L

Accident Date : 29/11/2021

Location : PIONEER SECTOR 2

TPA LG

Cecilin

FPSISDA10171

Model: MITSUBISHI FUSO FP5
(12/01/2016)

3P: SL1000Z (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front o/s head lamp <i>cracked</i>	800 1,450.60		
2	1 pc	Front o/s head lamp cover <i>cracked</i>	345.60	✓	
3	1 pc	Front o/s signal lamp <i>cracked</i>	390 865.60		
4	1 pc	Front o/s signal lamp cover <i>cracked</i>	211.50	✓	
5	1 pc	Front bumper <i>Red Dented</i>	2259 2,885.40		
6	1 pc	Front bumper o/s corner garnish <i>cracked</i>	210.00	✓	
7	1 pc	Front o/s step aluminium <i>cracked</i>	310.00	✓	
8	1 pc	Front o/s step bracket <i>new</i>	910.40	X	
9	1 pc	Front o/s step garnish middle <i>cracked</i>	856.40	✓	
10	1 pc	Front o/s step garnish lower <i>cracked</i>	328.70	✓	
		Front o/s step reflector <i>Missing</i>	45		
		Sub-Total:	8,374.20	0.00	0.00
			25%	0%	0%
		After Less %:	6,280.65	0.00	0.00
		Labour			
			4317.15		
1		To remove and replace front damage parts	900.00	500	
2		To spray painting.	700.00	500	
3		To check wiring.	1030 100.00	30	
4		To re-set electrical system.	380.00	X	
		Sub-Total:	2,080.00		
		Total:	8,360.65		
		After Less 20%:	6,688.52		

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

24 hr accident call

Acknowledged by Repairer

Signature:

Date:

Adrian L
1/s 01/12/21.

03 days.

Mobil 1

total: 5347.15

4/s: 4.2K

