

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21012142/GEA3Q2**Date:** 16/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070044102-01
<b>Claimant Vehicle No :</b>	SHA3070C	<b>Insured Vehicle No :</b>	SLG4808G
Date of Loss:	29/11/2021	Nature of Claim:	TP
		Claim No:	7977162990SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA3070C</b>	Engine No:	G4LEKU210480
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVKU146088
Reg. Date:	14/05/2019 (Man. Year: 2019)	Odometer:	416563 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,721.40	561.00	1,160.40	67.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	640.00	420.00	39.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,781.40</b>	<b>1,201.00</b>	<b>1,580.40</b>	<b>56.82</b>
<b>+ GST 7.00/7.00% (S\$)</b>	194.70	84.07	110.63	56.82
<b>Nett Amount (S\$)</b>	<b>2,976.10</b>	<b>1,285.07</b>	<b>1,691.03</b>	<b>56.82</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$125.19/day) (S\$)</b>		250.38		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
	<b>Nett Liability (S\$)</b>	<b>1,637.45</b>		

INSPECTION

Date of Assignment:	30/11/2021	
Date Inspected:	30/11/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

**Adjuster:** XING GUO QIANG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	459.40 FL	*- FL
2	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
6	1		*LICENCE LAMP	Not Necessary	85.30 FL	*- FL
7	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 FS	*100.00 FS
8	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 FS	*100.00 FS
9	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
10	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,044.25</b>	<b>651.25</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	322.85	90.25
<b>Total Parts (\$\$)</b>	<b>1,721.40</b>	<b>561.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE / REFIX REVERSE SENSOR	New	60.00	40.00
<b>Gross Labour Cost (\$)</b>			<b>1,060.00</b>	<b>640.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**