

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21012145/KTF3E2**Date:** 13/12/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000784317

Claimant Vehicle No : SLX2534U**Insured Vehicle No :** SLS1585E

Date of Loss: 27/11/2021

Nature of Claim: TP Claim No: 266050

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLX2534U**

Make & Model: HONDA CIVIC, 1.5 VTi (A)

Engine No: R16A13005982

Reg. Date: 25/07/2008 (Man. Year: 2008)

Chassis No: JHMFD46208S201937

Colour: White

Odometer: 215739 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Nexen 8 mm

Rear Left Side: Nexen 8 mm

Front Right Side: Nexen 8 mm

Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,082.28	2,248.28	834.00	27.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	850.00	550.00	39.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,482.28	3,098.28	1,384.00	30.88
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	4,482.28	2,450.00	2,032.28	45.34
+ GST 7.00/7.00% (S\$)	313.76	171.50	142.26	45.34
Nett Amount (S\$)	4,796.04	2,621.50	2,174.54	45.34

INSPECTION

Date of Assignment: 30/11/2021

Date Inspected: 01/12/2021 Inspected At:

E M Solution Pte Ltd (HQ)
160 Sin Ming Drive,, #03-18, Sin Ming Autocity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2021)
Parts:	143	HONDA CIVIC 1.5 VTi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX2534U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Cut	1,036.20 FL	*903.20 FL
2	1		*HEADLAMP BRACKET RH	Serviceable	48.50 FL	*- FL
3	1		*FRT FENDER RH	Bent / Buckled	631.50 FL	*537.50 FL
4	1		*FRT FENDER LINER RH	Serviceable	112.20 FL	*- FL
5	1		*FRT BUMPER	Buckled / Dented	841.80 FL	*638.00 FL
6	2		*FRT BUMPER SIDE RETAINER L/R	Distorted	86.40 FL	*86.40 FL
7	1		*FRT BUMPER FOG LAMP RH	Mtg Cracked	275.30 FL	*275.30 FL
8	1		*FOG LAMP GARNISH RH	Serviceable	78.40 FL	*- FL
9	1		*FRT GRILLE	Dented	226.20 FL	*226.20 FL
10	1		*FRT GRILLE CHROME MOULDING	Serviceable	196.20 FL	*- FL
11	1		*FRT GRILLE HONDA LOGO	Not Necessary	43.80 FL	*- FL
12	1		*FRT PANEL TOP GARNISH	Serviceable	95.10 FL	*- FL
13	1		*SET FRT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
14	1		*SET FRT GRILLE CLIPS	Necessary	35.00 FS	*35.00 FS
15	1		*SET TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
16	1		*SET FRT FENDER LINER CLIPS	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,816.60	2,781.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	734.32	533.32
Total Parts (\$\$)	3,082.28	2,248.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	100.00	20.00
2	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	500.00	400.00
3	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	600.00	400.00
4	TO REMOVE & RENEW REVERSE SENSOR	New	100.00	0.00
5	RUST PROOFING ON AFFECTED PORTIONS	New	100.00	30.00
Gross Labour Cost (\$)			1,400.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >