

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012146/VGS3Q2**Date:** 14/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070129636
Claimant Vehicle No :	SHB8344A	Insured Vehicle No :	SMV2220Z
Date of Loss:	30/11/2021	Nature of Claim:	TP
		Claim No:	6380238162SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8344A		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No:	D4FBGZ127655
Reg. Date:	16/08/2017 (Man. Year: 2016)	Chassis No:	TMAD281UVHJ131318
Colour:	Silver	Odometer:	358137 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,813.07	466.00	2,347.07	83.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	770.00	860.00	52.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,443.07	1,236.00	3,207.07	72.18
+ GST 7.00/7.00% (S\$)	311.01	86.52	224.49	72.18
Nett Amount (S\$)	4,754.08	1,322.52	3,431.56	72.18
+ Loss of Use (2.0 x S\$40.00/day) (S\$)		80.00		
+ Car Rental (2.0 x S\$62.06/day) (S\$)		124.12		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,528.64		
Global Sum Settlement (S\$)		1,500.00		

INSPECTION

Date of Assignment:	30/11/2021		
Date Inspected:	06/12/2021	Inspected At:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	2.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LOWER GARNISH	Repair	362.61 FL	*- FL
2	1		*TAILGATE WEATHERSTRIP	Serviceable	276.98 FL	*- FL
3	1		*TAILGATE STRIKER	Serviceable	36.50 FL	*- FL
4	1		*EMBLEM CRDI	Serviceable	29.40 FL	*- FL
5	1		*EMBLEM HYUNDAI LOGO	Serviceable	29.40 FL	*- FL
6	1		*EMBLEM I30	Serviceable	29.40 FL	*- FL
7	1		*REAR BUMPER	Repair	811.11 FL	*- FL
8	1		*REAR BUMPER SPONGE	Serviceable	79.20 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Serviceable	815.64 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT CENTRE	Serviceable	79.20 FL	*- FL
11	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Serviceable	104.40 FL	*- FL
12	2		*REAR BUMPER N/S & O/S REFLECTOR	Serviceable	107.50 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
14	1		*SET REVERSE SENSOR	Cut	280.00 FS	*280.00 FS
15	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*100.00 FS
16	1		*SET TAILGATE LOWER GARNISH CLIPS	Necessary	38.00 FS	*38.00 FS
17	1		*SET END PANEL INNER GARNISH CLIPS	Serviceable	38.00 FS	*- FS
18	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
19	1		*SUNDRY	Serviceable	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					3,365.34	466.00
- List Item Discount on L Items 20.00/20.00% (S\$)					552.27	0.00
Total Parts (S\$)					2,813.07	466.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	80.00	50.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE OF THE END PANEL ,TAILGATE ETC	New	650.00	360.00
4	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE ,TAILGATE LOWER GARNISH ,END PANEL	New	600.00	360.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	0.00
Gross Labour Cost (\$)			1,630.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >