thousan elth and to how 25/10/21 1430

PREMIER AUTOMOTIVE SERVICES PTE LTD 2 change wp

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORT 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG.200707743D G5T RFG-200707743D

B-Dec-21

| D-Defre | | | 1 | |
|---------------|---|--|----|-----------------|
| ESTIMA | TE REPAIR BILL FOR HYUN | DAI 130(A) WAGON REGN NO: SHB 8344 A | | |
| Colimin | C NEW YORK | | 3 | 362 61 KV |
| 1 pc | Tailgate lower garnish | | 3 | 276 98 X 5, C |
| 1 pc | Tailgate weatherstrip | | 3 | 36.50 XSU C |
| 1 pc | Tailgate Striker | | \$ | 29 40 X 5,16 |
| 1 pc | Emblem CRDI | | s | 29.40 x546 |
| 1 pc | Emblem Hyundai logo | | \$ | 29 40 x 30 C |
| 1 pc | Emblem 130 | | \$ | 811 11 XY |
| 1 pc | Rear bumper | | \$ | 79.20 X5.0C |
| 1 pc | Rear bumper sponge | | \$ | 815.64 xcc |
| 1 pc | Rear bumper reinforcement | | \$ | 79 20 XXVC |
| 1 pc | Rear bumper reinforcement centre | | \$ | 104.40 YSU 4 |
| 2 pcs | Rear bumper n/s & o/s side bracket @ \$52.20 | | \$ | 107.50 xxx c |
| 2 pcs | Rear bumper n/s & o/s reflecto | or Herri Land | \$ | 2,761.34 |
| | | LKK Auto Consultants hence notify the Repairer of the following: Less 20% | \$ | 552.27 |
| | | To resurvey before/after spray painting | \$ | 2,209.07 |
| | | To display damaged part(s) during resurvey | | |
| S/NETT | - | Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis | s | 48.00/nec |
| 1 set | Rear bumper clips | No illegal modification(s) is allowed | 5 | 280.00/(4+ |
| 1 set | Reverse sensor | Supplementary item(s) must be resurveyed <u>and</u> in a blood to find a parameter from leaverness Company | | , |
| 1 set | Tailgate stickers | is subject to final approval from Insurance Company | \$ | 100.00/nec |
| 1 set | Tailgate lower garnish clips | Acknowledged by Repairer | \$ | 38.00/ncc |
| | End panel inner garnish clips | Signature: | \$ | 38.00 × 10050 C |
| 1 set 1 pc | Rear number plate | Date: | \$ | 50.00 X ₩SVC |
| , pc | , | | • | 50.00 XSUC |
| | Sundry To dismantle and replace reverse sensor and test system | | \$ | |
| | | | \$ | 80.00 |
| | To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. | | | 180.00 XNN |
| | To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, tailgate, etc To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, To apply rustproofing on the repaired and replaced panels | | \$ | 650.00 360 |
| | | | \$ | 600.00 360 |
| | | | \$ | 120.00 X/VN |
| | , | Total | \$ | 4,443.07 |
| | | | | |

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.