

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012150/KTY3N2**Date:** 15/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00234512104

Claimant Vehicle No : SLZ6223E **Insured Vehicle No :** SJU3899A

Date of Loss: 27/11/2021 Nature of Claim: TP Claim No: SNM21D206896/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ6223E**

Make & Model: TOYOTA PRIUS HYBRID ALPHA, 1.8 S CVT (A) Engine No: 2ZR0A30053

Reg. Date: 11/05/2018 (Man. Year: 2017) Chassis No: ZVW400027337

Colour: Metallic Black Odometer: 303570 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: SUNWIDE 8 mm Rear Left Side: SUNWIDE 8 mm

Front Right Side: SUNWIDE 8 mm Rear Right Side: SUNWIDE 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,717.50	3,377.00	2,340.50	40.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	1,380.00	590.00	29.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,687.50	4,757.00	2,930.50	38.12
Approved Total (Overridden) (\$\$)		3,800.00		
(\$\$)	7,687.50	3,800.00	3,887.50	50.57
+ GST 7.00/7.00% (\$\$)	538.13	266.00	272.13	50.57
Nett Amount (\$\$)	8,225.63	4,066.00	4,159.63	50.57

INSPECTION

Date of Assignment: 01/12/2021

Date Inspected: 30/11/2021 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Dec 2021)

Parts: M1-MPV TOYOTA PRIUS HYBRID ALPHA 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ6223E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,096.00 FL	*929.00 FL
2	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	351.00 FL	*- FL
3	1		*REAR TAILGATE INNER LOCK	Dented	425.00 FL	*425.00 FL
4	1		*REAR TAILGATE PRIUS CX EMBLEM	Necessary	80.00 FL	*80.00 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	80.00 FL	*80.00 FL
6	1		*REAR TAILGATE TOYOTA EMBLEM	Not Necessary	80.00 FL	*- FL
7	1		*REAR WINDSCREEN MOULDING	Necessary	180.00 FL	*180.00 FL
8	1		*REAR TAIL LAMP LH	Mtg Cracked	691.00 FL	*630.00 FL
9	1		*REAR TAIL LAMP RH	Serviceable	691.00 FL	*- FL
10	1		*REAR TAIL LAMP BRACKET LH	Serviceable	60.00 FL	*- FL
11	1		*REAR TAIL LAMP BRACKET RH	Serviceable	60.00 FL	*- FL
12	1		*REAR BUMPER	Buckled	549.00 FL	*549.00 FL
13	1		*REAR BUMPER SIDE BRACKET LH	Distorted	95.00 FL	*95.00 FL
14	1		*REAR BUMPER SIDE BRACKET RH	Distorted	95.00 FL	*95.00 FL
15	1		*REAR END PANEL	Repair	696.00 FL	*- FL
16	1		*REAR FLOOR PANEL TOOLBOX TRAY	Dented	666.00 FL	*666.00 FL
17	1		*REAR FLOOR PANEL TRAY UPPER BOARD	Serviceable	542.00 FL	*- FL
18	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
20	1		*REAR BUMPER REVERSE SENSOR	Scratched	300.00 FS	*200.00 FS
21	1		*REAR END PANEL UPPER COVER CLIPS	Necessary	30.00 FS	*30.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
23	1		*REAR END PANEL JOINT SEALANT	Not Necessary	60.00 FS	*- FS
24	1		*REAR TAILGATE WEATHERSTRIPE (50%)	Cut	178.50 FS	*119.00 FS
25	1		*REAR END PANEL UPPER COVER	Mtg Distorted	175.00 FL	*175.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,370.50	4,353.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,653.00	976.00
Total Parts (\$\$)	5,717.50	3,377.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	700.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE,REAR BUMPER,REAR END PANEL & ETC	New	700.00	600.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS,REAR WINDSCREEN MOULDING,REAR WINDSCREEN SEALANT & ETC.TO EFFECT REPLACE OF REAR TAILGATE	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC.BACK TO ORIGONAL OPERATIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (\$\$)			1,970.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >