

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012155/AVY3N2**Date:** 14/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00094792100

Claimant Vehicle No : SMX8588M **Insured Vehicle No :** SMZ6517X

Date of Loss: 25/11/2021 Nature of Claim: TP Claim No: SNM21D206836/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX8588M**

Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A) Engine No: 2AZJ004681

Reg. Date: 05/09/2013 (Man. Year: 2013) Chassis No: ACR507118894

Colour: Black Odometer: 98729 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,360.00	3,417.62	2,942.38	46.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	720.00	1,550.00	68.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,630.00	4,137.62	4,492.38	52.06
Approved Total (Overridden) (\$\$)		3,300.00		
(\$\$)	8,630.00	3,300.00	5,330.00	61.76
+ GST 7.00/7.00% (\$\$)	604.10	231.00	373.10	61.76
Nett Amount (\$\$)	9,234.10	3,531.00	5,703.10	61.76

INSPECTION

Date of Assignment: 30/11/2021

Date Inspected: 01/12/2021 Inspected At: E-Care Auto Services Pte Ltd (HQ)
Block 51, Ubi Ave 1, #01-29, Paya Ubi Ind Pk
Singapore 408933

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2022)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX8588M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,890.00 FL	*981.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	N/s Necessary	115.00 FL	*57.50 FL
3	1		*FRONT BUMPER LOWER GRILLE	Deformed	320.00 FL	*320.00 FL
4	1		*FRONT CENTER GRILLE	Not Necessary	495.00 FL	*- FL
5	1		*FRONT CENTER GRILLE EMBLEM	Not Necessary	294.00 FL	*- FL
6	1		*FRONT HEADLAMP LH	Cut	2,394.00 FL	*2,190.00 FL
7	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	112.00 FL	*- FL
8	1		*FRONT FOG LAMP LH	Cracked	210.00 FL	*210.00 FL
9	1		*FRONT FOG LAMP COVER LH	Damaged	95.00 FL	*95.00 FL
10	1		*FRONT TOWING CAP	Not Necessary	65.00 FL	*- FL
11	1		*FRONT REINFORCEMENT BAR	Not Necessary	320.00 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Not Necessary	790.00 FL	*- FL
13	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	210.00 FL	*- FL
14	1		*FRONT FENDER INNER SHIELD LH	Torn	160.00 FL	*160.00 FL
15	1		*AIR FILTER TANK	Cracked	225.00 FL	*225.00 FL
16	1		*FOG LAMP BRACKET LH	Damaged	280.00 FL	*160.00 FL
17	1		*FRONT BUMPER SPONGE	Cracked	105.00 FL	*105.00 FL
18	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
20	1		*FRONT NUMBER PLATE C/W GARNISH	Not Necessary	50.00 FS	*- FS
21	1		*FRONT SUPPORT PANEL SEAL	Not Necessary	50.00 FS	*- FS
22	1		*FRONT CENTER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*FRONT FOG LAMP COVER CLIPS	Necessary	50.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,380.00	4,543.50
- List Item Discount on L Items 25.00/25.00% (\$)	2,020.00	1,125.88
Total Parts (\$)	6,360.00	3,417.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD AND REMOVE AND REFIT ABOVE PARTS	New	800.00	400.00
2	TO PUTTY,RE-SPRAY PAINTING AFFECTED AREAS	New	800.00	250.00
3	TO RUST PROOF AFFECTED AREAS	New	120.00	40.00
4	TO CONDUCT DIAGNOSTIC SYSTEM	New	200.00	0.00
5	TO REMOVE AND REFIT FRONT AIRCOND CONDENSER AND TOP UP GAS	New	150.00	0.00
6	TO CHECK AND RECTIFY WIRING	New	100.00	30.00
7	TO REPLACE FRONT SENSOR AND CHECK	New	100.00	0.00
Gross Labour Cost (\$)			2,270.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >