

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012158/AGS3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700006332
Claimant Vehicle No :	SBD83R	Insured Vehicle No :	SLN46C
Date of Loss:	28/11/2021	Nature of Claim:	TP
		Claim No:	3311430773SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBD83R	Engine No:	CYG019196
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Chassis No:	WAUZZZ4G2HN100282
Reg. Date:	19/03/2018 (Man. Year: 2017)	Odometer:	67408 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,242.75	19,610.96	10,631.79	35.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,540.00	3,500.00	3,040.00	46.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,782.75	23,110.96	13,671.79	37.17
Approved Total (Overridden) (S\$)		18,500.00		
(S\$)	36,782.75	18,500.00	18,282.75	49.70
+ GST 7.00/7.00% (S\$)	2,574.79	1,295.00	1,279.79	49.70
Nett Amount (S\$)	39,357.54	19,795.00	19,562.54	49.70
+ Car Rental (14.0 x S\$120.00/day) (S\$)		1,680.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		21,602.45		
Global Sum Settlement (S\$)		21,600.00		

INSPECTION

Date of Assignment:	30/11/2021		
Date Inspected:	30/11/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	11.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOT LID	Buckled	3,580.00 FL	*3,580.00 FL
2	1	*BOOT LID BADGE	Necessary	98.80 FL	*98.80 FL
3	1	*BOOT LID EMBLEM A6	Necessary	96.20 FL	*96.20 FL
4	1	*BOOT LID EMBLEM TFSI	Necessary	97.30 FL	*97.30 FL
5	1	*BOOT LID INNER LOCK	Not Necessary	486.70 FL	*- FL
6	1	*BOOT LID WEATHERSTRIP	Not Necessary	289.70 FL	*- FL
7	1	*BOOT LID INNER TRIM	Not Necessary	498.60 FL	*- FL
8	1	*BOOT LID OUTER CHROME GARNISH	Necessary	498.20 FL	*498.20 FL
9	2	*BOOT LID LAMPS	N/S Cut / O/S Cracked	2,059.60 FL	*1,900.00 FL
10	2	*BOOT LID LAMPS INNER SEALER	Not Necessary	80.00 FL	*- FL
11	1	*REAR BUMPER	Distorted	2,676.80 FL	*2,676.80 FL
12	1	*REAR BUMPER SIDE RETAINERS	O/S Cracked	331.60 FL	*165.80 FL
13	1	*REAR BUMPER ATTACHMENT RETAINERS	O/S Damaged	193.80 FL	*95.90 FL
14	1	*REAR BUMPER CENTER RETAINERS	Not Necessary	278.90 FL	*- FL
15	1	*REAR BUMPER BOTTOM GARNISH	Not Necessary	186.50 FL	*- FL
16	1	*REAR BUMPER REINFORCEMENT	Bent	826.90 FL	*826.90 FL
17	2	*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	373.80 FL	*- FL
18	1	*REAR BUMPER LOWER SKIRT	Deformed	587.80 FL	*355.00 FL
19	2	*REAR BUMPER LOWER BRACKETS	Not Necessary	257.60 FL	*- FL
20	1	*REAR BUMPER REVERSE SENSOR (4 PCS)	Damaged (1 PCS ONLY)	1,143.60 FL	*285.90 FL
21	4	*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	211.60 FL	*100.00 FL
22	1	*REAR BUMPER REVERSE SENSOR WIRE HARDNESS	Not Necessary	897.60 FL	*- FL
23	1	*REAR BUMPER TOWING COVER	Not Necessary	65.90 FL	*- FL
24	1	*END PANEL	Dented	1,600.75 FL	*963.00 FL
25	1	*END PANEL TOP TRIM	Not Necessary	208.90 FL	*- FL
26	1	*SPARE TYRE PANEL TOP BOARD	Not Necessary	495.00 FL	*- FL
27	1	*SPARE TYRE PANEL TOP TOOL SPONGE	Not Necessary	198.70 FL	*- FL
28	1	*TAILLAMPS	O/S Cracked	2,373.80 FL	*1,186.90 FL
29	1	*TAILLAMP PANEL	Dented	685.90 FL	*345.00 FL
30	2	*TAILLAMP INNER SEALER	Not Necessary	86.00 FL	*- FL
31	1	*TAILLAMPS LOWER BRACKETS	O/S Cracked	309.40 FL	*154.70 FL
32	2	*SET TAILLAMPS CLIPS	Necessary	50.00 FL	*20.00 FL
33	1	*REAR EXHAUST SILENCER	Bent	2,189.60 FL	*1,504.00 FL
34	2	*REAR EXHAUST MOUNTINGS	Torn	251.20 FL	*45.00 FL
35	2	*REAR EXHAUST TIP GARNISH	Dented	773.40 FL	*366.70 FL
36	1	*REAR EXHAUST GASKET	Damaged	60.50 FL	*60.50 FL
37	1	*REAR FENDER RH	Distorted	4,654.80 FL	*4,654.80 FL
38	1	*REAR FENDER INNER TRIM RH	Not Necessary	489.60 FL	*- FL
39	1	*REAR FENDER INNER COWLING RH	Torn	198.70 FL	*198.70 FL
40	1	*REAR FENDER FUSED BOX	Cracked	987.60 FL	*750.00 FL
41	1	*REAR SIDE WINDSCREEN RH	Not Necessary	398.70 FL	*- FL
42	1	*REAR SIDE WINDSCREEN MOULDING RH	Necessary	128.90 FL	*128.90 FL
43	1	*REAR WINDSCREEN MOLDING	Necessary	168.90 FL	*168.90 FL
44	1	*REAR WINDSCREEN SEAL	Necessary	60.00 FL	*60.00 FL
45	1	*REAR FENDER AIR DUCT RH	Deformed	78.50 FL	*78.50 FL
46	1	*REAR EXHAUST ALUMINIUM HEAD SHIELD	Crumpled	425.60 FL	*172.00 FL
47	1	*SET BODY PANEL JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
48	2	*REAR EXHAUST CHROME PIPE	Not Necessary	360.00 FS	*- FS
49	1	*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
50	1	*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*50.00 FS
51	1	*SET REAR FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*30.00 FS
52	2	*SET REAR TAILLAMPS CLIPS	Not Necessary	30.00 FS	*- FS
53	1	*SET BOOTLID INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
54	1	*SET END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
55	1	*SET REAR WINDSCREEN SEALANT	Repeated	80.00 FS	*- FS

Report was unsubmitted during this print-out.

6/20/22, 3:36 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	33,511.95 21,774.40
					- List Item Discount on L Items 10.00/10.00% (\$\$)	3,269.20 2,163.44
					Total Parts (\$\$)	30,242.75 19,610.96
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,600.00	1,400.00
2	SPRAY PAINTING	New	2,200.00	1,300.00
3	CHECK WIRING ON TAILLAMPS	New	120.00	30.00
4	ANTI RUST	New	120.00	100.00
5	TO REMOVE/REFIT FUEL TANK FOR FENDER REPLACEMENT	New	200.00	80.00
6	REMOVE AND INSTALL CARPET AND SEAT	New	250.00	100.00
7	REMOVE AND INSTALL REVERSE SENSOR	New	150.00	60.00
8	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	250.00	100.00
9	TO REPROGRAM AND ERASE FAULT CODE	New	400.00	150.00
10	TO REMOVE /REFIT REAR WINDSCREEN	New	150.00	120.00
11	TO REMOVE/REFIT REAR FENDER GLASS	New	100.00	60.00
Gross Labour Cost (\$\$)			6,540.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >