

Accident Photo



Accident Photo



Accident Photo



VEHICLE INSPECTION REPORT

To: Siow Boon Hwee
C/o: Aldrin Automotive
No.1 Kaki Bukit Ave 6 #02-22
Autobay, Singapore 417883

Date : 16 August 2017
Our ref : AA/08/1701/TP

Accident Date : 28 July 2017
Inspection Date : 02 August 2017
Repairer Name : Aldrin Automotive
No.1 Kaki Bukit Ave 6 #02-22
Autobay, Singapore 417883

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SKS 7309 J
Make / Model : Nissan GT-R
Chassis No : R35004341
Engine No : VR38006051A

Year / Capacity : 2010 / 3799 cc
Colour : Gold
Mileage : 98712

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	255/40 R20	5 mm	Sport
Front Offside	: Bridgestone	255/40 R20	5 mm	Sport
Rear Nearside	: Bridgestone	255/40 R20	5 mm	Sport
Rear Offside	: Bridgestone	255/40 R20	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s front portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 54 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 25,700.00** on a contractual basis.

Under normal circumstances, the repair period would be about 8 (Eight) working days.

SCL APPRAISER PTE LTD

Vehicle Registration No: SKS 7309 J

Our Ref No: AA/08/1701/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPECIAL NETT ITEMS

1	Front n/s headlamp with HID assy	Damage	\$ 4,997.30	\$ 4,997.30
1	Front bumper	Damage	\$ 4,800.60	\$ 4,800.60
1	Front bumper side retainer	Damage	\$ 237.00	\$ 237.00
1	Front bumper signal lamp	Damage	\$ 210.20	\$ 210.20
1	Front n/s fender	Damage	\$ 2,699.30	\$ 2,699.30
1	Front n/s fender inner shield	Damage	\$ 564.40	\$ 564.40
1	Front n/s fender "GTR" emblem	Necessary	\$ 350.60	\$ 350.60
1	Front n/s fender side air vent	Damage	\$ 377.00	\$ 377.00
1	Front n/s fender inner shield clip (1 set)	Necessary	\$ 50.00	\$ 50.00
1	Front n/s wheel hub with bearing	Damage	\$ 1,356.20	\$ 1,356.20
1	Front shock absorber (1 set)	Damage	\$ 3,800.00	\$ 3,800.00
1	Front n/s knuckle arm	Damage	\$ 2,860.00	\$ 2,860.00
1	Front n/s lower arm	Damage	\$ 2,391.00	\$ 2,391.00
1	Front n/s top arm	Damage	\$ 1,123.40	\$ 1,123.40
1	Front n/s drive shaft	Intact	\$ 3,510.60	
1	Front n/s door	Repair	\$ 8,005.30	
1	Front n/s door glass	Intact	\$ 2,667.40	
1	Front n/s door side mirror	Damage	\$ 1,500.70	\$ 1,500.70
1	Front n/s tyre (Depreciation)	Damage	\$ 600.00	\$ 300.00
1	Front n/s sport rim	Damage	\$ 1,500.00	\$ 1,500.00
Total Cost - Special Nett items			\$ 43,601.00	\$ 29,117.70

Total cost of parts

\$ 43,601.00 \$ 29,117.70

LCL APPRAISER PTE LTD

Vehicle Registration No: SKS 7309 J

Our Ref No: AA/08/1701/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 43,601.00	\$ 29,117.70

LABOUR

1	To tow accident vehicle to workshop.	\$ 150.00	\$ 150.00
2	To check wiring , lighting and resetting headlamps focussing.	\$ 80.00	\$ 50.00
3	To remove and refit front undercarriage.	\$ 450.00	\$ 350.00
4	To conduct wheel alignment.	\$ 180.00	\$ 150.00
5	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00
6	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00	\$ 1,200.00
7	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00	\$ 1,000.00

GRAND TOTAL

\$ 47,661.00	\$ 32,077.70
---------------------	---------------------

C L APPRAISER PTE LTD

Vehicle Registration No: SKS 7309 J

Our Ref No: AA/08/1701/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 25,700.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser

