



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 7309J (SKE 666Y)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT N/S HEADLAMP WITH HID ASSY	REPLACED	4,997.30	3,950.50
1	FRONT BUMPER	REPAIRED SEE LABOUR	4,800.60	-
1	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	237.00	-
1	FRONT BUMPER SIGNAL LAMP	REPLACED	210.20	130.00
1	FRONT N/S FENDER	REPLACED	2,699.30	2,380.00
1	FRONT N/S FENDER INNER SHIELD	REPLACED	564.40	295.80
1	FRONT N/S FENDER "GTR" EMBLEM	REPLACED	350.60	350.60
1	FRONT N/S FENDER SIDE AIR VENT	NOT NECESSARY	377.00	-
1	SET FRONT N/S FENDER INNER SHIELD CLIP	REPLACED	50.00	15.00
1	FRONT N/S WHEEL HUB WITH BEARING	REPLACED	1,356.20	950.30
1	SET FRONT SHOCK ABSORBER	NOT NECESSARY	3,800.00	-
1	FRONT N/S KNUCKLE ARM	REPLACED	2,860.00	1,890.00
1	FRONT N/S LOWER ARM	REPLACED	2,391.00	2,391.00
1	FRONT N/S TOP ARM	REPLACED	1,123.40	1,123.40
1	FRONT N/S DRIVE SHAFT	INTACT	3,510.60	-
1	FRONT N/S DOOR	REPAIRED SEE LABOUR	8,005.30	-
1	FRONT N/S DOOR GLASS	INTACT	2,667.40	-
1	FRONT N/S DOOR SIDE MIRROR	REPLACED	1,500.70	1,500.70
1	FRONT N/S TYRE	NOT NECESSARY	600.00	-
1	FRONT N/S SPORT RIM	REPLACED	1,500.00	1,000.00
			43,601.00	15,977.30
<u>LABOUR</u>				
	TO TOW ACCIDENT VEHICLE TO WORKSHOP.	NOT NECESSARY	150.00	-
	TO CHECK WIRING, LIGHTING AND RESETTING HEADLAMPS FOCUSING.		80.00	30.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		450.00	150.00
	TO CONDUCT WHEEL ALIGNMENT.		180.00	60.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		100.00	40.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT N/S DOOR.		1,600.00	500.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	500.00
			4,060.00	1,280.00
GRAND TOTAL			47,661.00	17,257.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,800.00

Report Ref No. CS/LAW21012162/Dvf3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.