79	
B. FEN: CS LAW	21012162/DV73
	SKS 7309J (JB HOV 2030
	Veh No: (SKE 666Y) YT Regn. Dec 12010:
ont: Date:	
THE THE THE THE RES OD RES / EVA / HV / MV	Type: M.Cycle Bas Van Lorry Taxi Prime Mover
Installation No.	Truck/Trailer or
Wor mis	Make: Missen GT-R as 3799
	Colour Purple . A.C. Insurad Still RINA
	Sp. Reading 150994 TRadio insured Still May 184
GBE 2499G	Eng/No:- VR38006051A
RT/EK/208/2018/zx	CNG: R35004341 =
CP/6803/17/PD (AA).aa	Gen. Cond: Good / Fair / Poor / Burní
Expess:	Siesting: incoder / Jammed / Leaked / Burnt or
(Cheristecon) ·	Brake: horder / Jammed / Leaked / Burnt or
	Modi: NII SATO ARID OF
	Tyre Size: F: 255 (407-20
(Policy Condition) Rennant The veh had commenced its N/S 0/5	≥ 285 357.20
Refit at a lie ver had commenced its N/S O/S	Be I DO IN I EVISO AT LE LE LITTE I MILE I OLI SOLI LINI SOLITA
Bal or Maket Value:	TOYOTYDED OF Scidgestine
IDAC Amilianti Rport Consistent? : Yes or No	R/Bal 4 THE R/Bal 4
GIA / PR Sear: Consistent? : Yes or No	LBal 4 mm LBal 4 mm
Est Repair 6 days Res.: Yes of No	D.D.A 28/07/217 D.D.I 06/12/2121
Linna Sum 3 Val.: Yes or No	5. Survey held at 66 Upp Sergioon View
CA / REV / REP. / 24 HRS	Des. of Damages: Fri Rear O/S N/S U/C Rootios or
Date:Person Contacted: Vehicle: IN / 0	OUT
Date /Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
SJE Physica Re-inspect	h to
2202 272 To Sibnit 4/513,8001	- with 6 dys 7 m - 1.
(Red 11,900, 46%)	·
·	
Date/Time, File Pass in? Prefit. Report	Days Of Repair: 6
1) Dais/Time, File Return to?	Resurvey No. of Trip: Survey Faé:
- 22/2/22-typist	Transportagions
Add	Fee: Site insp (\$)_c+rs
	to The Tries of the State of th

47A Edgefield Plains #13-16 Singapore 828714 Hp: 90688689 Email: clappraiser@yahoo.com Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Siow Boon Hwee

Date

: 16 August 2017

C/o: Aldrin Automotive

Our ref

: AA/08/1701/TP

No.1 Kaki Bukit Ave 6 #02-22

Autobay, Singapore 417883

Accident Date

: 28 July 2017

Type of Survey

: Third Party

Inspection Date

: 02 August 2017

Repairer Name

: Aldrin Automotive

No.1 Kaki Bukit Ave 6 #02-22 Autobay, Singapore 417883

PARTICULARS OF VEHICLE

Registration No

: SKS 7309 J

Year / Capacity

: 2010 / 3799 cc

Make / Model

: Nissan GT-R

Colour

: Gold

Chassis No

: R35004341

Mileage

: 98712

Engine No

: VR38006051A

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	255/40 R20	5 mm	Sport
Front Offside	: Bridgestone	255/40 R20	5 mm	Sport
Rear Nearside	: Bridgestone	255/40 R20	5 mm	Sport
Rear Offside	: Bridgestone	255/40 R20	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s front portion. (Details refer to the photographs attached)

Enclosed number of photographs:

54

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$ 25,700.00 on a contractual basis.

Under normal circumstances, the repair period would be about 8 (Eight) working days.

CCL APPRAISER PTE LTD

Vehicle Registration No: SKS 7309 J

Our Ref No: AA/08/1701/TP

Qty Description		Conditions		Repairer's		Revised		
Qış	Description	Description Conditions			Amount			
	SPECIAL NETT ITEMS							
						3951.57		
1	Front n/s headlamp with HID assy	Damage	\$	4,997.30	\$	4,997.30		
1	Front bumper	Damage	\$	4,800.60	\$	4,800.60 R		
1	Front bumper side retainer	Damage	\$	237.00	\$	237.00 HH		
1	Front bumper signal lamp	Damage	\$	210.20	\$	210.20		
1	Front n/s fender	Damage	\$	2,699.30	\$	2,699.30		
1	Front n/s fender inner shield	Damage	\$	564.40	\$	564.40		
1	Front n/s fender "GTR" emblem	Necessary	\$	350.60	\$	350.60		
1	Front n/s fender side air vent	Damage	\$	377.00	\$	377.00 MH		
1	Front n/s fender inner shield clip (1 set)	Necessary	\$	50.00	\$	50:00 15/-		
1	Front n/s wheel hub with bearing	Damage	\$	1,356.20	\$	1,356.20 950		
1	Front shock absorber (1 set)	Damage	\$	3,800.00	\$	3,800.00 HH		
1	Front n/s knuckle arm	Damage	\$	2,860.00	\$	2,860.00 1890		
1	Front n/s lower arm	Damage	\$	2,391.00	\$	2,391.00		
1	Front n/s top arm	Damage	\$	1,123.40	\$	1,123.40		
1	Front n/s drive shaft	Intact	\$	3,510.60				
1	Front n/s door	Repair	\$	8,005.30				
1	Front n/s door glass	Intact	\$	2,667.40				
1	Front n/s door side mirror	Damage	\$	1,500.70	\$	1,500.70		
1	Front n/s tyre (Depreciation)	Damage	\$	600.00	\$	300.00 ₩₩		
1	Front n/s sport rim	Damage	\$	1,500.00	\$	1,500.00 1000		
	Total Cost - Special Nett items		\$	43,601.00	\$	29,117.70		

15,977.30

Total cost of parts

\$ 43,601.00	\$ 29,117.70

CL APPRAISER PTE LTD

Vehicle Registration No: SKS 7309 J

Our Ref No: AA/08/1701/TP

S/No	Description		Repairer's Estimate		Revised Amount	
	Total cost of parts c/f	\$	43,601.00	\$	29,117.70	
	<u>LABOUR</u>					
1	To tow accident vehicle to workshop.	\$	150.00	\$	150.00	
2	To check wiring, lighting and resetting headlamps focussing.	\$	80.00	\$	50.00	
3	To remove and refit front undercarriage.	\$	450.00	\$	350.00	
4	To conduct wheel alignment.	\$	180.00	\$	150.00	
5	To apply undercoating on repaired and replaced panel.	\$	100.00	\$	60.00	
6	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	1,600.00	\$	1,200.00	
7	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,500.00	\$	1,000.00 500	
GRAND TOTAL	GRAND TOTAL	\$	47,661.00	\$	32,077.70	
			7257.30			
		LISI	7257.30	_		

6 days.



Vehicle Registration No: SKS 7309 J

Our Ref No: AA/08/1701/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 25,700.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser