




SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)**1/53: Photographs of Damaged Items****2/53: Photographs of Damaged Items****3/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)**4/53: Photographs of Damaged Items****5/53: Photographs of Damaged Items****6/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)**7/53: Photographs of Damaged Items****8/53: Photographs of Damaged Items****9/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)**10/53: Photographs of Damaged Items****11/53: Photographs of Damaged Items****12/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)**13/53: Photographs of Damaged Items****14/53: Photographs of Damaged Items****15/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)**16/53: Photographs of Damaged Items****17/53: Photographs of Damaged Items****18/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ).**19/53: Photographs of Damaged Items****20/53: Photographs of Damaged Items****21/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)**22/53: Photographs of Damaged Items****23/53: Photographs of Damaged Items****24/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)**25/53: Photographs of Damaged Items****26/53: Photographs of Damaged Items****27/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ).**28/53: Photographs of Damaged Items****29/53: Photographs of Damaged Items****30/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ).



31/53: Photographs of Damaged Items



32/53: Photographs of Damaged Items



33/53: Photographs of Damaged Items

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ).**34/53: Photographs of Damaged Items****35/53: Photographs of Damaged Items****36/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ).



37/53: Photographs of Damaged Items



38/53: Photographs of Damaged Items



39/53: Photographs of Damaged Items

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)



40/53: Photographs of Damaged Items



41/53: Photographs of Damaged Items



42/53: Photographs of Damaged Items

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ).**43/53: Photographs of Damaged Items****44/53: Photographs of Damaged Items****45/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ)**46/53: Photographs of Damaged Items****47/53: Photographs of Damaged Items****48/53: Photographs of Damaged Items**

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ).



49/53: Photographs of Damaged Items



50/53: Photographs of Damaged Items



51/53: Photographs of Damaged Items

SLK1213X - Submitted by: FWD Singapore Pte. Ltd. (HQ).



52/53: Odometer Reading



53/53: Fault Lights