



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 899M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER	DAMAGED	278.00	278.00
2	FORK INNER TUBES	DAMAGED	1,660.00	1,660.00
2	FORK OUTER TUBES	DAMAGED	1,620.00	1,620.00
1	FORK UNDER BRACKET	INTACT	945.00	-
2	FRONT BRAKE DISCS	DAMAGED	700.00	700.00
1	FRONT SPORT RIM	DAMAGED	900.00	850.00
1	FRONT RIM SHAFT	NECESSARY	105.00	105.00
1	TOP FAIRING	DAMAGED	515.00	515.00
1	N/S AIR -INTAKE TUBE	DAMAGED	235.00	205.00
1	HEADLAMP	DAMAGED	668.00	668.00
1	LAMPSTAY	DAMAGED	385.00	256.00
1	FRONT SIGNAL	DAMAGED	98.00	90.00
2	SIDE FAIRINGS	DAMAGED	1,240.00	1,240.00
2	N/S SIDE INNER FAIRINGS	DAMAGED (1 PCS ONLY)	480.00	425.00
2	HANDLE -BARS	DAMAGED	220.00	220.00
2	HANDLE-BAR ENDS	DAMAGED	84.00	60.00
1	O/S SIDE MIRROR	DAMAGED	125.00	120.00
1	BRAKE LEVER	NOT NECESSARY	95.00	-
1	CLUTCH LEVER	DAMAGED	95.00	85.00
1	CLUTCH ENGINE COVER	DAMAGED	328.00	256.00
2	FRONT FOOTRESTS	DAMAGED	110.00	100.00
2	FRONT FOOTREST BRACKETS	NOT NECESSARY	390.00	-
1	GEAR PEDAL	NOT NECESSARY	135.00	-
1	BRAKE PEDAL	NOT NECESSARY	145.00	-
2	REAR FOOTRESTS	NOT NECESSARY	196.00	-
2	REAR FOOTREST BRACKETS	NOT NECESSARY	430.00	-
2	EXHAUST PIPE ASSYS	DAMAGED	2,600.00	2,400.00
2	EXHAUST PIPE CHROME PROTECTORS	DAMAGED	370.00	370.00
1	EXHAUST CHROME PIPE	DAMAGED	95.00	95.00
1	REAR O/S TAILBOARD	DAMAGED	598.00	598.00

Report Ref No. CC2/MIDA21012167/Rpq2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR O/S TAILBOARD SIDE COVER	DAMAGED	255.00	255.00
1	REAR TAILLAMP	INTACT	420.00	-
1	RADIATOR	DAMAGED	925.00	850.00
1	RADIATOR FAN ASSY	DAMAGED	355.00	355.00
1	FUEL TANK	DAMAGED	1,185.00	850.00
1	FUEL TANK SIDE COVERS	DAMAGED	450.00	450.00
1	METER COVER	DAMAGED	285.00	205.00
	LESS 10% DISCOUNT		-1,972.00	-1,588.10
			17,748.00	14,292.90
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET STEERING CONE (SN)	NECESSARY	75.00	75.00
1	CLUTCH COVER GASKET (SN)	NECESSARY	28.00	28.00
4	SET ENGINE OIL -(BOTTLE) (SN)	NECESSARY	112.00	50.00
1	SET SIDE FAIRING SLIDER (SN)	DAMAGED	180.00	140.00
1	FRONT TYRE (SN)	NOT NECESSARY	400.00	-
			795.00	293.00
	<b><u>LABOUR</u></b>			
	TO PROVIDE TOWING SERVICE.		50.00	40.00
	TO CHECK ELECTRICAL SYSTEM ,WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO PROVIDE LABOUR CHARGES ,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS ,RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.		480.00	350.00
			610.00	420.00
<b>GRAND TOTAL</b>			<b>19,153.00</b>	<b>15,005.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>9,750.00</b>

Report Ref No. CC2/MIDA21012167/Rpq2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.