

**FINAL COST OF REPAIR**

(To be completed for only one type of item)

To: <div style="text-align: center; margin-top: 20px;">           HD TPT CENTRE EAST, TPTHUBEAST            BEDOK NODE            HD TPT RESOURCE, TPTHUBEAST            RESOURCE SUP IC, TPTHUBEAST            _____            Unit         </div>		From: <div style="text-align: center; margin-top: 20px;">           93FMD / MOS            _____         </div>	
Description of Item:		MAN 16.284 LAERC 5T	
Part/Reg No: <b>MID21324</b>		Original Value: -	
Quantity: <b>01</b>		CE/Non CE: -	
SAF 1222:		BB70/D/BDK/19/21	
Date:		01 October 2021	
MO/MR:		8202665707/19512633	
Date:		03 October 2021	
Description of Damages and Costs of Repairs:		Accident Job No: 8202665707/19512633	
		Date: 03 October 2021	
<u>S/N</u> 1) RH door 1/4 glass broken 1.1) RH door panel dented 1.2) RH door frame out of alignment 1.3) Remove and refit door assembly both door hinges to assist repair 1.4) Spray Paint on door outer panel after repair		<u>Incident Repair</u>  <u>Man-hours</u> 22.00	
<u>S/N</u>	<u>Materials Cost</u>	<u>Unit Price</u>	<u>Qty</u>
1)	Side Glass	\$271.99	1
2)	Adhesive	\$66.98	1
2)	Apg 820 Auto Lacquer - B. Green Matt	\$14.00	3
			<u>COST</u>
			\$271.99
			\$66.98
			\$42.00
<b>Base/LEO Area Office's Assessment of Damages</b>			
Labour Charges @ \$79.81 per hour X 22.00 hrs = \$1,755.82			
Total Cost of Parts / Materials Used = \$380.97			
Sub-contractor = -			
Assessment Fee = \$638.47			
Towing Service = \$550.36			
Total <u>\$3,325.62</u>			
Estimated Time for Repair:		22 Hr	

\*Delete whichever is not applicable

FINAL COST OF REPAIR