

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI21012183/GVF3N2**Date:** 27/12/2021**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT106848
<b>Claimant Vehicle No :</b>	SHC2908H	<b>Insured Vehicle No :</b>	GBE2806D
Date of Loss:	30/11/2021	Nature of Claim:	TP
		Claim No:	M2105537

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC2908H</b>		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU211729
Reg. Date:	14/05/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU146354
Colour:	Blue	Odometer:	391376 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	954.64	121.28	833.36	87.30
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,440.00	850.00	590.00	40.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,405.64</b>	<b>982.28</b>	<b>1,423.36</b>	<b>59.17</b>
<b>+ GST 7.00/7.00% (S\$)</b>	168.39	68.76	99.63	59.17
<b>Nett Amount (S\$)</b>	<b>2,574.03</b>	<b>1,051.04</b>	<b>1,522.99</b>	<b>59.17</b>

**INSPECTION**

Date of Assignment:	01/12/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	30/11/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2908H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER	Repair	430.90 FL	-	*- FL
2	10		*FRT BUMPER CLIPS	Not Necessary	22.00 FL	-	*- FL
3	1		*FRT FENDER LH	Repair	588.80 FL	-	*- FL
4	1		*FRT FENDER BLUE-DRIVE LH	Necessary	26.60 FL	-	*26.60 FL
5	1		*FRT FENDER ADVERTISEMENT STICKER LH	Necessary	100.00 F	-	*100.00 FS
					Sub Total (S\$)	1,168.30	126.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	213.66	5.32
					Total Parts (S\$)	954.64	121.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	TUFF KOTE	New	40.00	0.00
Gross Labour Cost (\$\$)			1,440.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >