

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012185/UEA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100434414-06
Claimant Vehicle No :	GBJ3162U	Insured Vehicle No :	GBE2760B
Date of Loss:	30/11/2021	Nature of Claim:	TP
		Claim No:	7289405623SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ3162U	Engine No:	1GD8346988
Make & Model:	TOYOTA HIACE, 2.8 D DX (A)	Chassis No:	GDH2012003530
Reg. Date:	15/03/2019 (Man. Year: 2018)	Odometer:	91347 km
Colour:	Silver		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,415.70	5,816.40	7,599.30	56.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,810.00	1,730.00	48.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,955.70	7,626.40	9,329.30	55.02
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	16,955.70	6,100.00	10,855.70	64.02
+ GST 7.00/7.00% (S\$)	1,186.90	427.00	759.90	64.02
Nett Amount (S\$)	18,142.60	6,527.00	11,615.60	64.02
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,129.00		
Global Sum Settlement (S\$)		7,120.00		

INSPECTION

Date of Assignment:	01/12/2021	
Date Inspected:	01/12/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,288.10 F	*- FL
2	1		*TAILGATE	Badly Dented	2,159.10 F	*2,159.10 FL
3	1		*TAILGATE REAR LOGO	Necessary	85.10 F	*85.10 FL
4	1		*TAILGATE HIACE STICKER	Necessary	68.00 F	*68.00 FL
5	1		*TAILGATE OUTER HANDLE	Grazed	341.10 F	*341.10 FL
6	1		*TAILGATE WEATHERSTRIP	Twisted	366.50 F	*366.50 FL
7	1		*TAILGATE INNER LOCK	Shorted / Jammed	398.50 F	*398.50 FL
8	1		*TAILGATE INNER LOCK COVER	Not Necessary	105.00 F	*- FL
9	1		*TAILGATE INNER TRIM	Torn	421.10 F	*421.10 FL
10	2		*TAILLAMPS	Cracked	798.20 F	*798.20 FL
11	2		*TAILLAMP LOWER GARNISHS	Repair	370.00 F	*- FL
12	2		*TAILLAMP HOUSING PANELS	Repair	998.00 F	*- FL
13	1		*REAR BUMPER	Distorted	651.20 F	*651.20 FL
14	1		*REAR BUMPER INNER STEP BRACKET	Bent	245.50 F	*245.50 FL
15	4		*REAR BUMPER INNER LOWER BRACKETS	Bent	100.00 F	*100.00 FL
16	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	250.00 F	*- FL
17	1		*REAR END PANEL OUTER	Badly Dented	945.10 F	*801.10 FL
18	1		*REAR END PANEL INNER	Repair	988.10 F	*- FL
19	1		*REAR END PANEL TOP PLATE	Serviceable	362.20 F	*- FL
20	1		*REAR SPARE TYRE BRACKET	Bent	399.80 F	*399.80 FL
21	1		*REAR EXHAUST	Not Necessary	985.10 F	*- FL
22	1		*REAR EXHAUST MOUNTING	Not Necessary	60.00 F	*- FL
23	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
24	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
25	1		*TAILGATE 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
26	1		*SET TAILGATE CORPORATE STICKER	Necessary	480.00 FS	*250.00 FS
27	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
28	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
29	1		*SET REAR BUMPER REVERSE SENSOR	Torn	280.00 FS	*200.00 FS
30	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,415.70	7,525.20
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,708.80
Total Parts (\$)	13,415.70	5,816.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	100.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE REFIX REAR EXHAUST	New	100.00	0.00
6	TO SPRAY RUST PROOFING	New	100.00	80.00
7	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,280.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	700.00
Gross Labour Cost (S\$)			3,540.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >