

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012186/ATCN2**Date:** 21/01/2022**REFERENCE**

Insured/Claimant:	CHAN POH LAM FELIX	Policy No:	1900246149
Date of Loss:	24/11/2021	Nature of Claim:	OD
		Claim No:	2172728237SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFG73G	Engine No:	CZD886477
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF34L1013705
Reg. Date:	14/11/2019 (Man. Year: 2019)	Odometer:	37977 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,582.00	6,930.40	18,651.60	72.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,852.00	2,772.00	4,080.00	59.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,434.00	9,702.40	22,731.60	70.09
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	32,034.00	9,302.40	22,731.60	70.96
+ GST 7.00/7.00% (S\$)	2,242.38	651.17	1,591.21	70.96
Nett Amount (S\$)	34,276.38	9,953.57	24,322.81	70.96

INSPECTION

Date of Assignment:	01/12/2021		
Date Inspected:	30/11/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BUMPER	Torn	2,161.00 FS	*922.00 FS
2	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	118.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE CENTER	Deformed	217.00 FS	*173.20 FS
4	1		*FRONT BUMPER GRILLE COVER	Not Necessary	51.00 FS	*- FS
5	2		*FRONT BUMPER GRILLE-LH/RH	Not Necessary	220.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Deformed	383.00 FS	*306.40 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	N/s Cracked	306.00 FS	*122.00 FS
9	1		*RADIATOR GRILLE	Cracked	1,433.00 FS	*1,146.40 FS
10	1		*RADIATOR STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
11	1		*RADIATOR CAP	Not Necessary	45.00 FS	*- FS
12	1		*RADIATOR BRACKET	Not Necessary	41.00 FS	*- FS
13	1		*FRONT CAMERA	Not Necessary	1,141.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	102.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	916.00 FS	*- FS
16	1		*FRONT BUMPER TOP COVER	Deformed	123.00 FS	*98.00 FS
17	1		*AIRCOND STICKER	Necessary	8.00 FS	*5.68 FS
18	2		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
19	2		*HORN-LH/RH	Not Necessary	267.00 FS	*- FS
20	2		*HORN BRACKET-LH/RH	Not Necessary	44.00 FS	*- FS
21	2		*HEADLIGHT MOUNTING-LH/RH	Not Necessary	236.00 FS	*- FS
22	2		*HEADLIGHT-LH/RH	Not Necessary	11,178.00 FS	*- FS
23	2		*LIFT CYLINDER-LH/RH	Not Necessary	420.00 FS	*- FS
24	1		*LIFT CYLINDER HOSE	Torn	80.00 FS	*63.44 FS
25	1		*BONNET	Dented	3,508.00 FS	*2,806.40 FS
26	1		*BONNET IMPACT PROTECTION-CENTER	Necessary	28.00 FS	*21.84 FS
27	1		*BONNET RELEASE ELEMENT	Not Necessary	58.00 FS	*- FS
28	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
29	1		*BONNET ATTACHMENT PARTS	Not Necessary	296.00 FS	*- FS
30	1		*FRONT RADIATOR AIR GUIDE-LH/RH	N/s Cracked	76.00 FS	*29.76 FS
31	1		*FRONT RADIATOR AIR GUIDE UPPER	Not Necessary	42.00 FS	*- FS
32	2		*FRONT WHEEL COVER-LH/RH	Necessary	536.00 FS	*428.80 FS
33	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
34	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
35	1		*SIGN CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
			Supplementary			
36	1		*FRONT BUMPER WIRING SET	Snapped	676.00 FS	*540.80 FS
			Supplementary			

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	25,582.00	6,930.40
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOTH HEADLIGHTS.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,500.00	1,100.00
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION	New	480.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,852.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >