

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012187/AVCE2**Date:** 03/10/2022**REFERENCE**

Insured/Claimant:	TAM YEE KEONG	Policy No:	2100499366	
Date of Loss:	29/11/2021	Nature of Claim:	OD	Claim No: 1076578970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK7680R		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN021943
Reg. Date:	25/01/2017 (Man. Year: 2016)	Chassis No:	WAUZZZF44HA055467
Colour:	Grey	Odometer:	59969 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,995.00	26,510.32	18,484.68	41.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,154.00	11,312.00	6,842.00	37.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	63,149.00	37,822.32	25,326.68	40.11
Approved Total (Overridden) (S\$)		32,000.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	62,549.00	31,400.00	31,149.00	49.80
+ GST 7.00/7.00% (S\$)	4,378.43	2,198.00	2,180.43	49.80
Nett Amount (S\$)	66,927.43	33,598.00	33,329.43	49.80

INSPECTION

Date of Assignment:	01/12/2021		
Date Inspected:	30/11/2021	Inspected At:	24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	14.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER ATTACHMENT PART (NPA)	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Damaged	71.00 FS	*56.32 FS
4	1		*FRONT BUMPER GRILLE	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Torn	210.00 FS	*167.60 FS
6	1		*FRONT BUMPER AIR GUIDE-LH	Cracked	63.00 FS	*50.08 FS
7	1		*RADIATOR GRILLE	Cracked	1,152.00 FS	*921.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Cut	135.00 FS	*108.00 FS
9	1		*FRONT BUMPER FOAM FILLER PIRECE	Not Necessary	124.00 FS	*- FS
10	1		*FRONT REINFORCEMENT BAR	Not Necessary	845.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION-LH	Damaged	36.00 FS	*28.72 FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
15	1		*FRONT REINFORCEMENT BAR BRACKET	Not Necessary	137.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	58.00 FS	*- FS
17	1		*HORN-LH	Not Necessary	126.00 FS	*- FS
18	1		*HORN BRACKET-LH	Not Necessary	29.00 FS	*- FS
19	1		*BONNET	Dented	3,246.00 FS	*2,596.80 FS
20	1		*BONNET ATTACHMENT PART	Not Necessary	412.00 FS	*- FS
21	1		*BONNET IMPACT PROTECTION-CENTER/LH/RH (3PCS)	Necessary	84.00 FS	*65.68 FS
22	1		*BONNET STRIKER	Not Necessary	50.00 FS	*- FS
23	1		*BONNET LOCK	Not Necessary	214.00 FS	*- FS
24	1		*FRONT FENDER-LH	Distorted	767.00 FS	*613.20 FS
25	1		*FRONT FENDER ATTACHMENT PART	Not Necessary	202.00 FS	*- FS
26	1		*FRONT FENDER CLOSING ELEMENT-LH	Distorted	72.00 FS	*57.52 FS
27	1		*FRONT FENDER BRACKET-LH	Distorted	35.00 FS	*27.92 FS
28	1		*FRONT FENDER BRACKET-CENTER	Not Necessary	49.00 FS	*- FS
29	1		*FRONT FENDER BRACKET-BACK	Not Necessary	32.00 FS	*- FS
30	1		*FRONT FENDER BRACE	Bent	118.00 FS	*94.40 FS
31	1		*FRONT WHEEL HOUSING LINER-LH	Deformed	240.00 FS	*191.60 FS
32	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART (NPA)	Not Necessary	0.00 FS	*- FS
33	1		*FRONT WHEEL SPOILER	Distorted	73.00 FS	*58.40 FS
34	1		*FRONT WHEEL SPOILER-LH	Distorted	35.00 FS	*27.76 FS
35	1		*FRONT FENDER STONE GUARD	Not Necessary	51.00 FS	*- FS
36	1		*FRONT FENDER LEDGE COVER	Damaged	31.00 FS	*24.64 FS
37	1		*FRONT FENDER LEDGE COVER-UPPER	Necessary	23.00 FS	*17.92 FS
38	2		*FRONT FENDER CONNECTING PLATE-LH	Repair	467.00 FS	*- FS
39	1		*HEADLIGHT-LH	Cracked	7,693.00 FS	*6,154.40 FS
40	1		*HEADLIGHT POWER MODULE	Not Necessary	761.00 FS	*- FS
41	1		*HEADLIGHT CONTROL UNIT	Not Necessary	751.00 FS	*- FS
42	1		*HEADLIGHT HOSE-LH	Not Necessary	36.00 FS	*- FS
43	3		*COMPENSATING PIECE	Not Necessary	122.00 FS	*- FS
44	1		*HEADLIGHT LIFT CYLINDER-LH	Damaged	210.00 FS	*167.60 FS
45	1		*CORRUGATED PIPE	Not Necessary	93.00 FS	*- FS
46	1		*LOCK CARRIER	Cracked	1,016.00 FS	*812.80 FS
47	1		*LOCK CARRIER BRACKET	Not Necessary	19.00 FS	*- FS
48	6		*COOLANT	Necessary	266.00 FS	*212.64 FS
49	1		*FRONT RADIATOR AIR GUIDE-LH	Not Necessary	28.00 FS	*- FS
50	1		*FRONT RADIATOR INNER AIR GUIDE-LH	Not Necessary	12.00 FS	*- FS
51	1		*FRONT RADIATOR AIR GUIDE-UPPER	Not Necessary	16.00 FS	*- FS
52	1		*REFRIGERANT LINE	Not Necessary	1,278.00 FS	*- FS
53	1		*FRONT WINDOW CHROME TRIM STRIP-LH	Not Necessary	307.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*FRONT WINDOW TRIM-LH	Not Necessary	257.00 FS	*- FS
55	1		*FRONT ALUMINIUM RIM-LH	Cut	1,297.00 FS	*1,037.60 FS
56	1		*FRONT SUB FRAME	Not Necessary	1,891.00 FS	*- FS
57	1		*FRONT WISHBONE	Bent	539.00 FS	*430.80 FS
58	1		*FRONT SUSPENSION GUIDE-LH	Bent	943.00 FS	*754.40 FS
59	2		*FRONT SUSPENSION ARM-UPPER	Bent	1,024.00 FS	*818.40 FS
60	1		*WHEEL BEARING HOUSING-LH	Damaged	968.00 FS	*774.00 FS
61	1		*SWIVEL JOINT	Bent	193.00 FS	*154.40 FS
62	1		*WHEEL HUB	Damaged	479.00 FS	*383.20 FS
63	1		*DOUBLE BALL BEARING	Damaged	246.00 FS	*196.80 FS
64	1		*SUSPENSION FORKS-LH	Not Necessary	264.00 FS	*- FS
65	2		*COUPLING ROD	Not Necessary	240.00 FS	*- FS
66	1		*ANTI ROLL BAR	Not Necessary	433.00 FS	*- FS
67	1		*SHOCK ABSORBER	Not Necessary	301.00 FS	*- FS
68	1		*DRIVE SHAFT	Not Necessary	2,650.00 FS	*- FS
69	1		*STEERING GEAR	Damaged	6,787.00 FS	*6,911.20 FS
70	1		*TIE ROD END	Bent	197.00 FS	*157.20 FS
71	1		*TRACK ROD	Not Necessary	99.00 FS	*- FS
72	1		*ACRYLIC SEALER	Not Necessary	180.00 FS	*- FS
73	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
74	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
75	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
76	1		*FRONT NUMBER PLATE	Necessary	60.00 FS	*60.00 FS
77	1		*SUNDRIES	Necessary	500.00 FS	*211.52 FS
78	1		*REFRIGERANT PIPE (Supplementary)	Bent	523.00 FS	*418.00 FS
79	1		*FRONT WHEEL SPOILER-RH (Supplementary)	Necessary	73.00 FS	*58.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	44,995.00	26,510.32
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
4	TO REMOVE AND REINSTALL AIRCON CONDENSER,ADDITIONAL RADIATOR AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,700.00	1,700.00
5	TO RENEW LHS FRONT FENDER INNER AIRCON CONDENSER COOLANT PIPE	New	280.00	280.00
6	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,LHS FRONT FENDER AND LHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT.TO REPAIR LHS UPPER A-PILLAR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS	New	6,650.00	2,750.00
7	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER,LHS FRONT FENDER TOP SUPPORT,BONNET,LHS UPPER A-PILLAR AND LHS FRONT DOOR	New	4,850.00	2,200.00
8	TO RENEW LHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
10	TO RE-APPLY PAINT COATING FOR DAMAGE AREA	New	380.00	380.00
11	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY LHF FRONT DOOR	New	280.00	280.00
Gross Labour Cost (\$\$)			18,154.00	11,312.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >