

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21012188/ANCE2**Date:** 01/11/2022**REFERENCE**

|                   |            |                  |            |                        |
|-------------------|------------|------------------|------------|------------------------|
| Insured/Claimant: | ZHANG XIAO | Policy No:       | 7210040873 |                        |
| Date of Loss:     | 26/11/2021 | Nature of Claim: | OD         | Claim No: 9981374769SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMZ5354E</b>                   |             |                   |
| Make & Model:               | AUDI A5, 2.0 SPORTBACK (A)        | Engine No:  | DEM031628         |
| Reg. Date:                  | 30/04/2021 (Man. Year: 2021)      | Chassis No: | WAUZZZF5XMA039440 |
| Colour:                     | White                             | Odometer:   | 5203 km           |
| Engine Capacity:            | 1984 cc                           |             |                   |
| Market Value/New Car Price: | S\$210,000.00                     |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 245/40 R18   | Rear Tyre Size:  | 245/40 R18   |
| Front Left Side:  | Hankook 6 mm | Rear Left Side:  | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

*The above values represent the remaining tyre tread depth*

| <b>COST OF CLAIMS</b>               | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                               | 97,034.00         | 60,941.92         | 36,092.08         | 37.20         |
| Miscellaneous Items                 | 0.00              | 0.00              | 0.00              |               |
| Labour                              | 31,794.00         | 17,412.00         | 14,382.00         | 45.23         |
| Paintwork Labour                    | 0.00              | 0.00              | 0.00              |               |
| Towing                              | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b> | <b>128,828.00</b> | <b>78,353.92</b>  | <b>50,474.08</b>  | <b>39.18</b>  |
| <b>- Excess (S\$)</b>               | 800.00            | 800.00            | 0.00              | 0.00          |
| <b>(S\$)</b>                        | 128,028.00        | 77,553.92         | 50,474.08         | 39.42         |
| <b>+ GST 7.00/7.00% (S\$)</b>       | 8,961.96          | 5,428.77          | 3,533.19          | 39.42         |
| <b>Nett Amount (S\$)</b>            | <b>136,989.96</b> | <b>82,982.69</b>  | <b>54,007.27</b>  | <b>39.42</b>  |

**INSPECTION**

|                             |            |               |                                                          |
|-----------------------------|------------|---------------|----------------------------------------------------------|
| Date of Assignment:         | 01/12/2021 |               |                                                          |
| Date Inspected:             | 30/11/2021 | Inspected At: | 24 Benoi Sector<br>Repairer: Premium Automobiles Pte Ltd |
| Estimated Period of Repair: | 22.0 days  |               |                                                          |

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                     | Condition                | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------------|--------------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                                   | Distorted                | 2,342.00 FS | *1,873.60 FS |
| 2   | 2   |          | *FRONT BUMPER SECURING STRIP                    | Not Necessary            | 71.00 FS    | *- FS        |
| 3   | 1   |          | *FRONT BUMPER GRILLE CENTER                     | Not Necessary            | 196.00 FS   | *- FS        |
| 4   | 1   |          | *FRONT BUMPER CLOSING ELEMENT - LOWER CENTER    | Not Necessary            | 262.00 FS   | *- FS        |
| 5   | 1   |          | *FRONT BUMPER SPOILER                           | Not Necessary            | 535.00 FS   | *- FS        |
| 6   | 2   |          | *FRONT AIR GUIDE - LH / RH                      | Not Necessary            | 126.00 FS   | *- FS        |
| 7   | 1   |          | *FRONT BUMPER CLOSING ELEMENT                   | Damaged                  | 262.00 FS   | *209.20 FS   |
| 8   | 1   |          | *FRONT BUMPER AIR GUIDE GRILLE - LH / RH        | N/S Cracked              | 270.00 FS   | *108.00 FS   |
| 9   | 2   |          | *FRONT BUMPER TRIM - LH / RH                    | Not Necessary            | 96.00 FS    | *- FS        |
| 10  | 1   |          | *FRONT RADIATOR TRIM CENTER                     | Not Necessary            | 114.00 FS   | *- FS        |
| 11  | 1   |          | *FRONT RADIATOR GRILLE                          | Smashed                  | 1,694.00 FS | *1,355.20 FS |
| 12  | 1   |          | *FRONT RADIATOR CAP                             | Smashed                  | 166.00 FS   | *132.80 FS   |
| 13  | 1   |          | *FRONT RADIATOR BRACKET                         | Cracked                  | 17.00 FS    | *12.96 FS    |
| 14  | 1   |          | *FRONT RADIATOR SECURING PLATE                  | Cracked                  | 11.00 FS    | *8.08 FS     |
| 15  | 1   |          | *FRONT RADIATOR CAMERA                          | Cracked                  | 1,141.00 FS | *912.80 FS   |
| 16  | 1   |          | *FRONT RADIATOR GRILLE CAMERA ADAPTER           | Broken                   | 198.00 FS   | *158.40 FS   |
| 17  | 1   |          | *FRONT CAMERA ADAPTER                           | Not Necessary            | 288.00 FS   | *- FS        |
| 18  | 1   |          | *FRONT BUMPER FOAM FILLER PIECE                 | Cracked                  | 146.00 FS   | *99.20 FS    |
| 19  | 1   |          | *FRONT BUMPER REINFORCEMENT BEAM                | Dented                   | 845.00 FS   | *675.60 FS   |
| 20  | 2   |          | *FRONT BUMPER GUIDE SECTION - LH / RH           | Damaged                  | 72.00 FS    | *57.44 FS    |
| 21  | 2   |          | *FRONT BUMPER BRACKET - LH / RH                 | Bent                     | 428.00 FS   | *342.40 FS   |
| 22  | 1   |          | *FRONT BUMPER TOP COVER                         | Cracked                  | 127.00 FS   | *101.60 FS   |
| 23  | 1   |          | *CAUTION STICKER                                | Necessary                | 14.00 FS    | *12.40 FS    |
| 24  | 1   |          | *AIR COND STICKER                               | Necessary                | 8.00 FS     | *6.64 FS     |
| 25  | 1   |          | *FRONT BUMPER LOCK CARRIER BRACKET              | Cracked                  | 137.00 FS   | *109.60 FS   |
| 26  | 2   |          | *FRONT BUMPER SUPPORT - LH / RH                 | Distorted                | 58.00 FS    | *44.96 FS    |
| 27  | 4   |          | *POP RIVET                                      | Necessary                | 4.00 FS     | *2.56 FS     |
| 28  | 2   |          | *HORN - LH / RH                                 | Not Necessary            | 252.00 FS   | *- FS        |
| 29  | 2   |          | *HORN SUPPORT - LH / RH                         | Not Necessary            | 58.00 FS    | *- FS        |
| 30  | 4   |          | *FRONT PARKING AID SENSOR - INNER / OUTER (NPA) | Not Necessary            | 0.00 FS     | *- FS        |
| 31  | 1   |          | *SET FRONT BUMPER WIRING                        | Not Necessary            | 405.00 FS   | *- FS        |
| 32  | 2   |          | *FRONT FENDER - LH / RH                         | N/S Buckled / O/S Dented | 2,120.00 FS | *1,696.00 FS |
| 33  | 1   |          | *FRONT FENDER ATTACHMENT PARTS                  | Not Necessary            | 53.00 FS    | *- FS        |
| 34  | 2   |          | *FRONT FENDER CLOSING ELEMENT - LH / RH         | Necessary                | 148.00 FS   | *118.08 FS   |
| 35  | 2   |          | *FRONT FENDER BRACKET - LH / RH                 | Bent                     | 70.00 FS    | *55.84 FS    |
| 36  | 10  |          | *POP RIVET                                      | Necessary                | 33.00 FS    | *26.40 FS    |
| 37  | 2   |          | *FRONT FENDER BRACKET CENTER - LH / RH          | Not Necessary            | 98.00 FS    | *- FS        |
| 38  | 2   |          | *FRONT FENDER BRACE - LH / RH                   | Not Necessary            | 236.00 FS   | *- FS        |
| 39  | 2   |          | *FRONT FENDER BRACKET BACK - LH & RH            | Not Necessary            | 70.00 FS    | *- FS        |
| 40  | 2   |          | *FRONT WHEEL HOUSING LINER - LH / RH            | Not Necessary            | 550.00 FS   | *- FS        |
| 41  | 1   |          | *FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS    | Not Necessary            | 169.00 FS   | *- FS        |
| 42  | 2   |          | *FRONT WHEEL SPOILER - LH / RH                  | Not Necessary            | 146.00 FS   | *- FS        |
| 43  | 2   |          | *FRONT SPOILER - LH / RH                        | Not Necessary            | 71.00 FS    | *- FS        |
| 44  | 2   |          | *FRONT STONE CHIP GUARD - LH / RH               | Not Necessary            | 102.00 FS   | *- FS        |
| 45  | 2   |          | *FRONT FENDER TRIM - LH / RH                    | Necessary                | 328.00 FS   | *262.40 FS   |
| 46  | 1   |          | *BONNET                                         | Distorted                | 3,312.00 FS | *2,649.60 FS |
| 47  | 1   |          | *BONNET ATTACHMENT PARTS                        | Not Necessary            | 123.00 FS   | *- FS        |
| 48  | 2   |          | *BONNET HINGE - LH / RH                         | Not Necessary            | 838.00 FS   | *- FS        |
| 49  | 1   |          | *BONNET IMPACT PROTECTION - CENTER / LH / RH    | Necessary                | 84.00 FS    | *65.68 FS    |
| 50  | 1   |          | *BONNET SOUND ABSORBER                          | Crumpled                 | 343.00 FS   | *274.40 FS   |
| 51  | 2   |          | *BONNET STRIKER - LH / RH                       | Damaged                  | 100.00 FS   | *79.84 FS    |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                 | Condition     | Repairer's   | Amount        |
|-----|-----|----------|---------------------------------------------|---------------|--------------|---------------|
| 52  | 2   |          | *BONNET LOCK                                | Damaged       | 427.00 FS    | *341.30 FS    |
| 53  | 1   |          | *BONNET BOWDEN CABLE - CENTER               | Damaged       | 58.00 FS     | *46.00 FS     |
| 54  | 1   |          | *BONNET RELEASE LEVER                       | Not Necessary | 14.00 FS     | *- FS         |
| 55  | 1   |          | *BONNET BOWDEN CABLE INNER - CENTER         | Damaged       | 58.00 FS     | *46.00 FS     |
| 56  | 1   |          | *BONNET LOCK CABLE                          | Damaged       | 74.00 FS     | *58.64 FS     |
| 57  | 1   |          | *BONNET FLAT CONNECTOR                      | Not Necessary | 13.00 FS     | *- FS         |
| 58  | 2   |          | *FRONT LEDGE LONG COVER - INNER / OUTER     | Broken        | 72.00 FS     | *56.48 FS     |
| 59  | 2   |          | *FRONT LEDGE SHORT COVER - INNER / OUTER    | Not Necessary | 32.00 FS     | *- FS         |
| 60  | 2   |          | *HEADLAMPS COVER - LH / RH                  | Cracked       | 88.00 FS     | *68.96 FS     |
| 61  | 2   |          | *FRONT FENDER LEDGE COVER - LH / RH         | Not Necessary | 144.00 FS    | *- FS         |
| 62  | 1   |          | *PLENUM CHAMBER                             | Not Necessary | 97.00 FS     | *- FS         |
| 63  | 2   |          | *GAS FILLED STRUT                           | Not Necessary | 241.00 FS    | *- FS         |
| 64  | 2   |          | *HEADLIGHT MATRIX BEAM - LH / RH            | Cracked       | 15,370.00 FS | *12,296.00 FS |
| 65  | 2   |          | *HEADLIGHT HOSE                             | Not Necessary | 71.00 FS     | *- FS         |
| 66  | 1   |          | *COMPENSATING PIECE<br>6 Pcs                | Broken        | 243.00 FS    | *193.28 FS    |
| 67  | 2   |          | *LIFT CYLINDER - LH / RH                    | Not Necessary | 396.00 FS    | *- FS         |
| 68  | 2   |          | *LIFT CYLINDER BRACKET - LH / RH            | Damaged       | 30.00 FS     | *12.32 FS     |
| 69  | 1   |          | *LIFT CYLINDER HOSE<br>(NPA)                | Not Necessary | 0.00 FS      | *- FS         |
| 70  | 1   |          | *RADIATOR COOLANT LOCK CARRIER              | Cracked       | 1,016.00 FS  | *812.80 FS    |
| 71  | 2   |          | *RADIATOR COOLANT SUPPORT - LH / RH         | Broken        | 76.00 FS     | *60.64 FS     |
| 72  | 1   |          | *FLUID RESERVOIR A/C CONDENSER              | Dented        | 622.00 FS    | *497.60 FS    |
| 73  | 1   |          | *REFRIGERANT PRESSURE SENSOR                | Not Necessary | 186.00 FS    | *- FS         |
| 74  | 1   |          | *REFRIGERANT HIGH PRESSURE SWITCH           | Not Necessary | 51.00 FS     | *- FS         |
| 75  | 1   |          | *REFRIGERANT SUCTION HOSE                   | Not Necessary | 167.00 FS    | *- FS         |
| 76  | 1   |          | *REFRIGERANT DISCHARGE HOSE                 | Not Necessary | 340.00 FS    | *- FS         |
| 77  | 1   |          | *REFRIGERANT COOLANT PIPE                   | Not Necessary | 248.00 FS    | *- FS         |
| 78  | 1   |          | *OUTSIDE TEMPERATURE SENSOR BRACKET         | Missing       | 19.00 FS     | *14.56 FS     |
| 79  | 1   |          | *OUTSIDE TEMPERATURE SENSOR                 | Not Necessary | 59.00 FS     | *- FS         |
| 80  | 1   |          | *AIR COOLER CHARGED                         | Not Necessary | 587.00 FS    | *- FS         |
| 81  | 1   |          | *AIR COOLER PRESSURE HOSE OUTER - RH        | Not Necessary | 357.00 FS    | *- FS         |
| 82  | 1   |          | *AIR COOLER PRESSURE HOSE INNER - RH        | Not Necessary | 427.00 FS    | *- FS         |
| 83  | 1   |          | *RADIATOR COOLER                            | Bent          | 655.00 FS    | *523.60 FS    |
| 84  | 1   |          | *RADIATOR CONTROL UNIT                      | Dented        | 1,880.00 FS  | *1,548.00 FS  |
| 85  | 1   |          | *RADIATOR ING                               | Broken        | 220.00 FS    | *176.00 FS    |
| 86  | 1   |          | *RADIATOR COOLANT<br>(6PCS)                 | Necessary     | 266.00 FS    | *212.64 FS    |
| 87  | 1   |          | *A/C COMPRESSOR OIL                         | Not Necessary | 622.00 FS    | *- FS         |
| 88  | 2   |          | *RADIATOR AIR GUIDE OUTER - LH / RH         | Cracked       | 64.00 FS     | *52.64 FS     |
| 89  | 3   |          | *RADIATOR AIR GUIDE INNER - UPPER / LH / RH | Cracked       | 48.00 FS     | *39.84 FS     |
| 90  | 1   |          | *RADIATOR AIR GUIDE LOWER                   | Cracked       | 22.00 FS     | *17.20 FS     |
| 91  | 1   |          | *RADIATOR COOLANT UPPER HOSE                | Not Necessary | 71.00 FS     | *- FS         |
| 92  | 1   |          | *RADIATOR CONNECTOR TUBE                    | Not Necessary | 54.00 FS     | *- FS         |
| 93  | 1   |          | *RADIATOR COOLANT INLET                     | Not Necessary | 71.00 FS     | *- FS         |
| 94  | 1   |          | *RADIATOR COOLANT HOSE                      | Not Necessary | 22.00 FS     | *- FS         |
| 95  | 1   |          | *RADIATOR BREATHER TUBE                     | Damaged       | 34.00 FS     | *26.88 FS     |
| 96  | 1   |          | *RADIATOR BREATHER TUBE UPPER               | Not Necessary | 53.00 FS     | *- FS         |
| 97  | 1   |          | *RADIATOR VENT HOSE UPPER CENTER            | Not Necessary | 40.00 FS     | *- FS         |
| 98  | 1   |          | *ENGINE TIMING CASE COVER - BOTTOM          | Not Necessary | 277.00 FS    | *- FS         |
| 99  | 1   |          | *ENGINE TIMING CASE COVER - UPPER           | Broken        | 240.00 FS    | *191.60 FS    |
| 100 | 2   |          | *CAMSHAFT MAGNET ADJUSTER                   | Not Necessary | 338.00 FS    | *- FS         |
| 101 | 1   |          | *THROTTLE VALVE ADAPTER                     | Not Necessary | 1,036.00 FS  | *- FS         |
| 102 | 1   |          | *THROTTLE INTAKE AIR DUCT - RH              | Broken        | 22.00 FS     | *17.20 FS     |
| 103 | 1   |          | *THROTTLE AIR GUIDE                         | Broken        | 53.00 FS     | *42.40 FS     |
| 104 | 1   |          | *AIR FILTER                                 | Not Necessary | 386.00 FS    | *- FS         |
| 105 | 1   |          | *THROTTLE INTAKE HOSE                       | Not Necessary | 95.00 FS     | *- FS         |
| 106 | 1   |          | *FRONT AIR MASS METER                       | Not Necessary | 567.00 FS    | *- FS         |
| 107 | 1   |          | *INTAKE MANIFOLD                            | Not Necessary | 856.00 FS    | *- FS         |
| 108 | 1   |          | *EXHAUST GAS TURBOCHARGER                   | Not Necessary | 5,405.00 FS  | *- FS         |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------------|---------------|-------------|--------------|
| 109 | 1   |          | *FRONT WINDSCREEN                      | Cracked       | 1,461.00 FS | *1,168.80 FS |
| 110 | 1   |          | *FRONT RAIN SENSOR GEL FOIL            | Necessary     | 137.00 FS   | *109.20 FS   |
| 111 | 1   |          | *FRONT RETAINING SPRING                | Necessary     | 21.00 FS    | *16.56 FS    |
| 112 | 1   |          | *FRONT SPRING CLIP                     | Necessary     | 21.00 FS    | *16.56 FS    |
| 113 | 1   |          | *FRONT CAMERA SILICONE PAD             | Necessary     | 98.00 FS    | *77.68 FS    |
| 114 | 1   |          | *PRIMER                                | Necessary     | 20.00 FS    | *15.76 FS    |
| 115 | 2   |          | *FRONT WATER DEFLECTOR STRIP - LH / RH | Not Necessary | 134.00 FS   | *- FS        |
| 116 | 1   |          | *FRONT DOOR - RH                       | Dented        | 3,884.00 FS | *3,107.20 FS |
| 117 | 1   |          | *FRONT DOOR OUTER SEAL - RH            | Necessary     | 222.00 FS   | *177.60 FS   |
| 118 | 1   |          | *BONDING AGENT                         | Not Necessary | 49.00 FS    | *- FS        |
| 119 | 1   |          | *CLEANING SOLUTION                     | Not Necessary | 68.00 FS    | *- FS        |
| 120 | 1   |          | *APPLICATOR                            | Not Necessary | 8.00 FS     | *- FS        |
| 121 | 1   |          | *FRONT DOOR CATCH - RH                 | Not Necessary | 120.00 FS   | *- FS        |
| 122 | 1   |          | *FRONT TYRE PRESSURE DATA PLATE        | Not Necessary | 37.00 FS    | *- FS        |
| 123 | 2   |          | *FRONT DOOR TRIM - LH / RH             | Not Necessary | 328.00 FS   | *- FS        |
| 124 | 1   |          | *AIRBAG                                | Activated     | 3,682.00 FS | *2,945.60 FS |
| 125 | 1   |          | *AIRBAG UNIT                           | Activated     | 4,374.00 FS | *3,499.20 FS |
| 126 | 2   |          | *AIRBAG HEAD UNIT - LH / RH            | Activated     | 3,726.00 FS | *2,980.80 FS |
| 127 | 1   |          | *AIRBAG CONTROL UNIT                   | Activated     | 2,112.00 FS | *1,689.60 FS |
| 128 | 3   |          | *AIRBAG CRASH SENSOR                   | Activated     | 1,146.00 FS | *916.80 FS   |
| 129 | 1   |          | *STEERING WHEEL                        | Cut           | 2,374.00 FS | *1,899.20 FS |
| 130 | 1   |          | *FRONT DASHBOARD                       | Torn          | 5,289.00 FS | *4,231.20 FS |
| 131 | 1   |          | *FRONT MOULDED HEADLINER               | Crumpled      | 2,048.00 FS | *1,638.40 FS |
| 132 | 2   |          | *FRONT SEAT BELT TENSIONER - LH / RH   | Activated     | 2,206.00 FS | *1,764.80 FS |
| 133 | 2   |          | *FRONT SEAT BELT ADJUSTER - LH / RH    | Activated     | 342.00 FS   | *273.60 FS   |
| 134 | 2   |          | *FRONT GRAB HANDLE                     | Damaged       | 283.00 FS   | *226.40 FS   |
| 135 | 2   |          | *REAR GRAB HANDLE - LH / RH            | Damaged       | 284.00 FS   | *226.40 FS   |
| 136 | 2   |          | *A-PILLAR TRIM - LH / RH               | Cut           | 408.00 FS   | *326.40 FS   |
| 137 | 2   |          | *B-PILLAR TRIM - LH / RH               | Not Necessary | 470.00 FS   | *- FS        |
| 138 | 2   |          | *D-PILLAR TRIM - LH / RH               | Not Necessary | 408.00 FS   | *- FS        |
| 139 | 1   |          | *FRONT NO PLATE                        | Missing       | 100.00 FS   | *100.00 FS   |
| 140 | 1   |          | *FRONT WINDSCREEN SEALANT              | Necessary     | 200.00 FS   | *200.00 FS   |
| 141 | 1   |          | *SUNDRIES                              | Necessary     | 1,000.00 FS | *251.10 FS   |
| 142 | 2   |          | *C-PILLAR TRIM - LH / RH               | Not Necessary | 298.00 FS   | *- FS        |
| 143 | 1   |          | *BATTERY FUSE UNIT                     | Necessary     | 533.00 FS   | *426.00 FS   |
|     |     |          | (Supplementary)                        |               |             |              |
| 144 | 1   |          | *1 SET SINGLE WIRES                    | Broken        | 70.00 FS    | *51.68 FS    |
|     |     |          | (Supplementary)                        |               |             |              |
| 145 | 1   |          | *OIL PRESSURE SWITCH CONNECTOR         | Broken        | 8.00 FS     | *5.92 FS     |
|     |     |          | (Supplementary)                        |               |             |              |
| 146 | 1   |          | *OIL PRESSURE SWITCH                   | Broken        | 51.00 FS    | *40.48 FS    |
|     |     |          | (Supplementary)                        |               |             |              |
| 147 | 1   |          | *POLY-V-BELT                           | Cut           | 60.00 FS    | *47.60 FS    |
|     |     |          | (Supplementary)                        |               |             |              |
| 148 | 1   |          | *BELT TENSIONER                        | Cut           | 459.00 FS   | *366.80 FS   |
|     |     |          | (Supplementary)                        |               |             |              |
| 149 | 1   |          | *STARTER GENERATOR                     | Bent          | 1,987.00 FS | *1,589.60 FS |
|     |     |          | (Supplementary)                        |               |             |              |
| 150 | 1   |          | *VIBRATION                             | Bent          | 427.00 FS   | *341.60 FS   |
|     |     |          | (Supplementary)                        |               |             |              |
| 151 | 1   |          | *BUTT CONNECTOR                        | Necessary     | 62.00 FS    | *48.96 FS    |
|     |     |          | 6PCS (Supplementary)                   |               |             |              |
| 152 | 1   |          | *1 SET SINGLE WIRES                    | Broken        | 63.00 FS    | *50.16 FS    |
|     |     |          | (Supplementary)                        |               |             |              |
| 153 | 1   |          | *WINDSCREEN DEFROSTER NOZZLE GRILLE    | Broken        | 123.00 FS   | *98.40 FS    |
|     |     |          | (Supplementary)                        |               |             |              |
| 154 | 1   |          | *WINDSCREEN DEFROSTER NOZZLE           | Broken        | 167.00 FS   | *133.60 FS   |
|     |     |          | (Supplementary)                        |               |             |              |
| 155 | 1   |          | *FLATCONTACT HOUSING WITH CABLE        | Broken        | 186.00 FS   | *148.80 FS   |
|     |     |          | (Supplementary)                        |               |             |              |
| 156 | 1   |          | *ROUND CONNECTOR HSG WITH CABLE        | Broken        | 259.00 FS   | *206.80 FS   |
|     |     |          | (Supplementary)                        |               |             |              |
| 157 | 1   |          | *FRT DOOR WINDOW SLOT SEAL-RH          | Bent          | 399.00 FS   | *318.80 FS   |
|     |     |          | (Supplementary)                        |               |             |              |

Report was unsubmitted during this print-out.

11/1/22, 11:08 AM

Adjuster Report

| No.                          | Qty | Part No. | Particulars                             | Condition | Repairer's | Amount              |
|------------------------------|-----|----------|-----------------------------------------|-----------|------------|---------------------|
| 158                          | 1   |          | *ADAPTER CABLE LOOM<br>(Supplementary)  | Damaged   | 319.00 FS  | *254.80 FS          |
| 159                          | 1   |          | *A/C PRESSURE SENSOR<br>(Supplementary) | Damaged   | 186.00 FS  | *148.80 FS          |
| F=Franchise part. S=SpcNett. |     |          |                                         |           |            |                     |
| Total Parts (S\$)            |     |          |                                         |           |            | 97,034.00 60,941.92 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                                                                                                                                          | Lab.Type | Repairer's       | Amount           |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|------------------|
| <b>Labour Items</b>             |                                                                                                                                                                                                                                                      |          |                  |                  |
| 1                               | TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT (NPA)                                                                                                                                                                                              | New      | 0.00             | 0.00             |
| 2                               | TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER                                                                                                                                                                                                   | New      | 800.00           | 0.00             |
| 3                               | TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID                                                                                                     | New      | 480.00           | 480.00           |
| 4                               | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS                                                                                | New      | 2,200.00         | 2,200.00         |
| 5                               | TO REMOVE CENTER CONSOLE, INSTRUMENT PANEL AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNITS, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS                            | New      | 3,600.00         | 3,600.00         |
| 6                               | TO PLACE VEHICLE ON CAR O-LINER                                                                                                                                                                                                                      | New      | 2,400.00         | 0.00             |
| 7                               | TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY LHS FRONT DOOR                                                                                                                 | New      | 280.00           | 0.00             |
| 8                               | TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES                                                                                                                                               | New      | 350.00           | 280.00           |
| 9                               | TO RENEW ENGINE THROTTLE BODY AND OTHER ENGINE COMPONENTS                                                                                                                                                                                            | New      | 780.00           | 780.00           |
| 10                              | TO RENEW FRONT WINDSCREEN                                                                                                                                                                                                                            | New      | 480.00           | 480.00           |
| 11                              | TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN                                                                                                                                                                                                           | New      | 400.00           | 400.00           |
| 12                              | TO CARRY OUT WATER SEEPAGE TEST ON FRONT WINDSCREEN                                                                                                                                                                                                  | New      | 200.00           | 150.00           |
| 13                              | TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, RHS FRONT DOOR AND BOTH HEADLIGHTS. TO REPAIR BOTH UPPER A-PILLAR. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New      | 8,000.00         | 4,500.00         |
| 14                              | TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH UPPER A-PILLAR AND BOTH FRONT DOORS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT                                                                                      | New      | 8,000.00         | 3,300.00         |
| 15                              | TO CARRY OUT PRE WHEEL ALIGNMENT TEST                                                                                                                                                                                                                | New      | 240.00           | 0.00             |
| 16                              | TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST REPAIR DIAGNOSTIC CHECK                                                                                                                                                                            | New      | 384.00           | 192.00           |
| 17                              | TO REPAIR BOTH FRONT FENDER TOP SUPPORT AND LHS FRONT CHASSIS COVER PLATE<br>(Supplementary)                                                                                                                                                         | New      | 1,600.00         | 500.00           |
| 18                              | TO RESPRAY BOTH FRONT FENDER TOP SUPPORT AND LHS FRONT CHASSIS COVER PLATE<br>(Supplementary)                                                                                                                                                        | New      | 1,600.00         | 550.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                                                                                                                      |          | <b>31,794.00</b> | <b>17,412.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >