

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI21012189/ETF3E2

Date: 26/04/2022

REFERENCE

Handling Insurer:	EQ Insurance Company Ltd	Policy No:	DMPPHQ21-005687
Claimant Vehicle No :	SNB5052R	Insured Vehicle No :	SKW2934R
Date of Loss:	29/11/2021	Nature of Claim:	TP
		Claim No:	DM21HO01787

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB5052R	Engine No:	M15AY236644
Make & Model:	TOYOTA YARIS CROSS, 1.5 X B-PKG CVT (A)	Chassis No:	JTDKBAB310L005996
Reg. Date:	26/08/2021 (Man. Year: 2021)	Odometer:	10189 km
Colour:	White		
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R16	Rear Tyre Size:	205/65R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,068.00	3,090.25	2,977.75	49.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,800.00	510.00	22.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,378.00	4,890.25	3,487.75	41.63
+ GST 7.00/7.00% (S\$)	586.46	342.32	244.14	41.63
Nett Amount (S\$)	8,964.46	5,232.57	3,731.89	41.63

INSPECTION

Date of Assignment:	03/12/2021	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	03/12/2021	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2022)
Parts:	M1-SUV	TOYOTA YARIS CROSS 1.5 X B-PKG CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB5052R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Not Necessary	1,710.00 FL	*- FL
2	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	171.00 FL	*- FL
3	1		*FRONT BUMPER	Broken	582.00 FL	*512.00 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Broken	172.00 FL	*172.00 FL
5	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FS
6	1		*FRONT FENDER LH	Dented	781.00 FL	*781.00 FL
7	1		*FRONT FENDER ARCH GARNISH LH	Cut	371.00 FL	*371.00 FL
8	1		*FRONT FENDER LOWER GARNISH LH	Not Necessary	271.00 FL	*- FL
9	1		*FRONT FENDER COWLING LH	Crushed	274.00 FL	*274.00 FL
10	10		*FRONT FENDER COWLING CLIPS	Necessary	40.00 FL	*20.00 FS
11	1		*SIDE MIRROR COVER LH	Repair	231.00 FL	*- FL
12	1		*FRONT DOOR EMBLEM - HYBRID	Necessary	121.00 FL	*121.00 FL
13	1		*REAR DOOR LH	Dented	1,716.00 FL	*1,716.00 FL
14	1		*REAR DOOR HANDLE LH	Repair	371.00 FL	*- FL
15	1		*REAR DOOR LOWER PROTECTOR LH	Not Necessary	371.00 FL	*- FL
16	1		*REAR DOOR REAR PROTECTOR LH	Not Necessary	381.00 FL	*- FL
17	1		*REAR FENDER LH	Repair	371.00 FL	*- FL
18	1		*SOUND PROOF INSULATOR	Necessary	80.00 FS	*80.00 FS
19	1		*FRONT DOOR LH - REPAIR (NPA)	Repair	-	-
20	1		*REAR FENDER LH - REPAIR (NPA)	Repair	-	-
21	1		*FUEL LID COVER LH - REPAIR (NPA)	Repair	-	-

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,064.00	4,077.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,996.00	986.75
Total Parts (S\$)	6,068.00	3,090.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO INSPECT FRONT LIGHTING MECHANISM & CHECK WIRING	New	80.00	30.00
2	TO REPAIR ON FRONT DOOR LH, REAR FENDER LH & FUEL LID COVER . TO REMOVE & REPLACE DAMAGED ITEMS, REALIGN CONNECTION	New	800.00	700.00
3	TO TRANSFER ITEMS INTO NEW DOOR	New	150.00	50.00
4	TO RUST PROOF ON REPAIRED AREAS	New	80.00	20.00
5	TO SPRAY PAINT ON REPAIRED AREAS	New	1,200.00	1,000.00
Gross Labour Cost (\$)			2,310.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >