

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21012193/R1vy3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 06/12/2021 SINGAPORE 068811 ATTN: KOH JANICE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 1820T** SMR 4588X Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03MN5 Excess (\$) 0.00 **KOH JANICE Assign Date** 30/11/2021 Assign From **Vehicle Particulars & Condition** 2. HONDA FIT 1.3GF CVT 1317 Make & Model C.C HIDDEN 2020 Engine No. Year of Reg. GK31345274 RED Chassis No. Colour Odometer 32585 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 175/70 R14 DUNLOP 6 mm 175/70 R14 DUNLOP L/H Front Tyre 6 mm 175/70 R14 DUNLOP R/H Rear Tyre 6 mm **DUNLOP** L/H Rear Tyre 175/70 R14 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 20/11/2021 01/12/2021 (04:26 PM) Inspect Date / Time Accident Date LIM MOTOR PTE LTD Survey held at 160 SIN MING DRIVE #05-20 SIN MING AUTOCITY SINGAPORE 575722 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Report Ref No. CS3/ASM21012193/R1vy3e2

Estimate Days of Repair

Inspected By

Automotive Assessor

5b.

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

5 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser