



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 2525T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED / TORN	1,190.00	1,190.00
1	SET REVERSE SENSOR	SHORTED	480.00	200.00
1	REAR BUMPER CENTRAL GARNISH	CUT	460.00	460.00
1	REAR BUMPER CORNER GARNISH	TO REPAIR SEE LABOUR	217.00	-
1	REAR BUMPER SPONGE	NOT NECESSARY	285.00	-
1	BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	830.00	-
1	REAR RIGHT LAMP	SERVICEABLE	450.00	-
1	REAR BOOTLID	TO REPAIR SEE LABOUR	3,180.00	-
2	REAR NUMBER PLATE LAMP @\$45.00	NOT NECESSARY	90.00	-
1	REAR WINDSCREEN RUBBER SEAL	NOT NECESSARY	851.00	-
1	REAR END INNER PENAL	TO REPAIR SEE LABOUR	1,235.00	-
	LESS 10% DISCOUNT		-926.80	-185.00
			8,341.20	1,665.00
	<u>LABOUR</u>			
	KNOCKING & WELDING BODYWORK. INCLUSIVE OF THE REPAIR OF REAR BUMPER CORNER GARNISH, BUMPER REINFORCEMENT, REAR BOOTLID AND REAR END INNER PENAL.		1,200.00	450.00
	RESPRAY REAR PORTION PAINT.		1,100.00	500.00
	REMOVE REAR WINDSCREEN & LABOUR.	NOT NECESSARY	180.00	-
	CHECK WIRING LABOUR.		150.00	20.00
	ANTI RUST AFFECTED PARTS.	NOT NECESSARY	200.00	-
			2,830.00	970.00
	GRAND TOTAL		11,171.20	2,635.00

Report Ref No. CS/FCI21012197/Uuf3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	-----------------

Report Ref No. CS/FCI21012197/Uuf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.