

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

CS/FC/21012197/4uf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

D21003317MVPC

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

27A 8 27887

Veh No:

551 25257

Yr Regn:

30/11/06

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA / Coupe

Make:

mer benz C180k c.c 1796

Colour:

black

A/C: Insured / Std / NI / NA

Sp. Reading

54644

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WD B203 746 2A 944620

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55 R16 Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/11/11

D.O.I.

1/12/11

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Car until 30-10-2026 2077k.

7/12/11 4/s \$2100 confirmed with Kei-lay 3 repair days
(RED \$8891.20; 81%)

Date/Time, File Pass to?

☐

Preli. Report

1) 7/12 TYPIST

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

Report Format: TP

Lump Sum / H.R. (\$ 2100)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

凱樑汽車服務

KAI LIANG MOTOR SERVICE

AUTOBAY @ KAKI BUKIT

BLK 1 KAKI BUKIT AVE 6 #01-101 SINGAPORE 417883

TEL: 67474189 FAX: 67431164

Email: kailiangmotorservice@gmail.com

not Authorised
4/s \$2100
3 days
1/11/21
Thuphathorey
30-11-2021

MS First Capital Insurance Limited

36, Robinson Road,

#16-01, City House

Singapore 068877

Our Ref: SJJ2525T

Your Ref: SLG5596K / Third party claim

Road Traffic Accident involving SJJ2525T and SLG5596K on 20/08/2021.

Third party claim against SLG5596K

SJJ2525T Repairing Quotation

	Parts Description	Amount SGD(\$)
1 set	Rear bumper	\$1190.00
	Reverse sensor	\$480.00
	Rear bumper central garnish	\$460.00
	Rear bumper corner garnish	\$217.00
	Rear bumper sponge	\$285.00
	Bumper reinforcement	\$830.00
	Rear right lamp	\$450.00
	Rear door Bootlid	\$3180.00
2 pcs	Rear number plate lamp @ \$45.00 / pc	\$90.00
	Rear windscreen rubber seal	\$851.00
	Rear end inner penal	\$1235.00
	Total before discount:	\$9268.00
	Less 10%	(\$926.80)
	Subtotal:	\$8341.20
	Nett:	
	Knocking & welding bodywork	\$1200.00
	Respray rear portion paint	\$1100.00
	Remove rear windscreen & labour	\$180.00
	Check wiring labour	\$150.00
	Anti rust affected parts	\$200.00
	Subtotal:	\$2650.00
	Amount Total:	\$10991.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1850
102
1665
970
2635