

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21012200/VTF3N2**Date:** 09/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100499366
Claimant Vehicle No :	SMN3174J	Insured Vehicle No :	SLK7680R
Date of Loss:	29/11/2021	Nature of Claim:	TP
		Claim No:	1076578970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3174J	Engine No:	2NRX475512
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	MHFZ28H3000064381
Reg. Date:	31/07/2019 (Man. Year: 2019)	Odometer:	209871 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	RAPID 6 mm	Rear Left Side:	RAPID 6 mm
Front Right Side:	RAPID 6 mm	Rear Right Side:	RAPID 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/12/2021		
Date Inspected:	06/12/2021	Inspected At:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$78,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER UPPER RH	Dented	0.00 F	*- F
3	1		*REAR BUMPER LOWER	Scratched	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER BRACKET	Distorted	0.00 F	*- F
6	1		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
7	1		*REAR BUMPER REFLECTOR RH	Scratched	0.00 F	*- F
8	1		*REVERSE SENSOR	Cut	0.00 F	*- F
9	1		*TAILGATE	Dented	0.00 F	*- F
10	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
11	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
12	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >