

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21012203/KGA3Q2**Date:** 05/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SMJ2858Y **Insured Vehicle No :** SNB6704L  
 Date of Loss: 27/11/2021 Nature of Claim: TP Claim No: MFL2021D0005207

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ2858Y**  
 Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B14100269  
 Reg. Date: 27/02/2019 (Man. Year: 2019) Chassis No: JHMGK3850KS208086  
 Colour: Metallic Yellow Odometer: 33972 km  
 Engine Capacity: 1318 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15  
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	831.84	0.00	831.84	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	280.00	320.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,431.84</b>	<b>280.00</b>	<b>1,151.84</b>	<b>80.44</b>
<b>+ GST 7.00/7.00% (S\$)</b>	100.23	19.60	80.63	80.44
<b>Nett Amount (S\$)</b>	<b>1,532.07</b>	<b>299.60</b>	<b>1,232.47</b>	<b>80.44</b>
<b>+ Loss of Use (1.0 x S\$60.00/day) (S\$)</b>		60.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>367.05</b>		

INSPECTION

Date of Assignment: 01/12/2021  
 Date Inspected: 03/12/2021 Inspected At: Ah Lim Motor Company (AMK)  
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK  
 Autopoint  
 Singapore 568047  
 Estimated Period of Repair: 1.0 days

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2022)
<b>Parts:</b> 144	HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ2858Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Repair	529.40 FL	*- FL	
2	1		*REAR BUMPER GRILLE LH	Serviceable	31.90 FL	*- FL	
3	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	23.50 FL	*- FL	
4	5		*REAR BUMPER CLIPS	Not Necessary	17.50 FL	*- FL	
5	1		*SET REVERSE SENSOR	Serviceable	350.00 FS	*- FS	
					<b>Sub Total (S\$)</b>	<b>952.30</b>	<b>0.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	120.46	0.00
					<b>Total Parts (S\$)</b>	<b>831.84</b>	<b>0.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE ALL DAMAGED PARTS ,TO CUT & WELD TO KNOCK & REPAIR REAR INNER PANEL INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	300.00	80.00
2	TO SPRAY REAR BUMPER	New	300.00	200.00
			<b>Gross Labour Cost (\$\$)</b>	<b>280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >