

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012205/UVY3N2**Date:** 09/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: SJX4068J

**Claimant Vehicle No :** GBJ9760D **Insured Vehicle No :** SJX4068J

Date of Loss: 27/11/2021 Nature of Claim: TP Claim No: SNM21D206909/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBJ9760D**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KDB014766

Reg. Date: 11/11/2019 (Man. Year: 2019) Chassis No: JTFHT02P800249755

Colour: Green Odometer: 70709 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195R15 Rear Tyre Size: 195R15

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,780.00	1,070.00	710.00	39.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	319.20	319.20	0.00	0.00
Paintwork Labour	604.50	604.50	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,703.70</b>	<b>1,993.70</b>	<b>710.00</b>	<b>26.26</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	189.26	139.56	49.70	26.26
<b>Nett Amount (\$\$)</b>	<b>2,892.96</b>	<b>2,133.26</b>	<b>759.70</b>	<b>26.26</b>

**INSPECTION**

Date of Assignment: 30/11/2021 Present Location: Jin Auto Services Pte Ltd (Defu)

Date Inspected: 06/01/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)  
Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ9760D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		1,780.00 F	*1,070.00 F
						F=Franchise part.
Total Parts (S\$)					1,780.00	1,070.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINTWORK LABOUR	New	604.50	604.50
<u>Labour Items</u>				
2	TOTAL LABOUR CHARGE	New	319.20	319.20
Gross Labour Cost (\$\$)			923.70	923.70

Report was unsubmitted during this print-out.

< END OF ESTIMATES >