

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **63J9760D**

at Workshop m/s **Tina Anh**

of _____

Insured: **SJX 4068J**

Policy No. _____

Claims No. **SNM21D206909/C02/TOHHS**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: **\$70k.**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Scén: _____ Consistent? : Yes or No

Est. Repairs: **4** days Res.: Yes or No

Lum Sum: **13.1** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: **LIA \$20047**Date / Time Action / Instruction **on 9/2****ports \$1070**

2/3/22 informed Jones R/P \$1993.70 (red 710, 26%)

Veh No: **63J9760D** Yr Regn: **11/11/19**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: **Toyota Hiace** c.c. **2982**

Colour: **Green** A/C: **Insured / Std / NI / NA**

Sp. Reading: **70709** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **JTFHT027800249755**

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi: **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: **195-115** R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO / YOKO or

Front **6** mm Rear **6** mm

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **27/11/2021** D.O.I. **6/1/22**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 2/3/22-typist

Days Of Repair: **4**Resurvey No. of Trip: **2**

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$)

) \$ + RS \$ SI

☐

: Interview (\$)

) Photos

☐

: Tech. Invs (\$)

) Others

☐

: Weekend (\$)

)

Report Format : Merimen

Lump Sum / I.B.I. (\$ 1993.70)

TOTAL

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Insurer Reference: GBJ9760D
Repairer Reference: GBJ9760D - SJX4068J(TP-CTP)

Date calculated: 30/11/2021 11:26 AM

Full Report
Registration: GBJ9760D

Printed: 30/11/2021 11:26 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	JOUIS SEOW	Currency:	SGD
Claim Reference:	GBJ9760D	Date of Incident:	27/11/21
Estimated Repair Time:	7	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: TOYOTA
Model: HIACE
Sub Model: BASE MODEL
Model Sheet Number: 70 E4 01
Registration: GBJ9760D
VIN number: JTFHT02P800249755
Odometer: 66902

Model Specs

3.0 LTR 100/106 KW	WHEELBASE 3110MM	L/SLIDING DOOR	R/SLIDING DOOR
TWO COAT METALLIC	PREPARE OFF VEHICLE		

*not authorized
see
tel: 62563561
to be paid before 7 days.
4 days.
P/P \$ 1993.70*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*UEN
691H*


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner),Tread (Right Outer),Tread (Right Middle), mm						Condition
------------	---	--	--	--	--	--	-----------

Spare Tyre Brand Tread (Spare), mm

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B216	RENEW RIGHT SLIDING DOOR INCLUDES: R + R AND ALIGN SLIDING DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		19.0	79.80
420111	R + R WHEEL COVER/S		2.0	8.40
B420	RENEW REAR BUMPER INCLUDES: REAR BUMPER AND REQUIRED ATTACHED PARTS R + R		5.0	21.00
3482	R/RR SIDE PANEL REPAIR		50.0*	210.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		7.60	76.0	319.20
Total of Labour				319.20

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	R/R SLIDING DOOR NEW PART PAINTING	26.0
	REAR BUMPER NEW PART PAINT K1R	8.0
	R/RR SIDE PANEL REPAIR PAINTING <50%	28.0

Paint Material Per Part

Code	Description	Price SGD
1782	R/R SLIDING DOOR NEW PART PAINTING	85.66
2581	REAR BUMPER NEW PART PAINT K1R	34.44
3482	R/RR SIDE PANEL REPAIR PAINTING <50%	60.40

Labour Cost - Paint

Factor	Hrs	WU	Price SGD
Time Paint		62.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	92.0	386.40

Material Cost - Paint

	Price SGD
New Part Painting	85.66
New Part Painting - Plastic K1R	34.44
Repair Painting	60.40
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	218.10

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
1782	R/R SLIDING DOOR	67003 26310	Original ✓	780.00	780.00
2581	REAR BUMPER	52159 26470	Original ✓	200.00	200.00
9560	R/R WHEEL COVER	42602 26010	Original ✓	90.00	90.00
1000	REAR BUMPER CLIPS	CLIPS	Original	30.00	30.00
1001	COMPANY ARTWORKS	ARTWORK	Original	680.00	680.00
					0.00
Savings					0.00
Subtotal					1,780.00
Total					1,780.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

parts \$1070

Final Calculation

	SGD	SGD
Parts		
Total Parts	1,780.00	1,780.00
Labour Time Base 10 WU/h		
Total 76.0 WU X 42.00 SGD/h	319.20	
Total of Labour		319.20
Paint Work Time Base 10 WU/h		
Labour Cost 92.0 WU X 42.00 SGD/h	386.40	
Material Cost	218.10	
Total Paint Including Material		604.50
Repair Cost Excludes GST		2,703.70
GST (+7.00%)		189.26
Repair Cost Included GST		2,892.96

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.