

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012206/UPA3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900166047-01
Claimant Vehicle No :	PC4957H	Insured Vehicle No :	SMP3552R
Date of Loss:	01/12/2021	Nature of Claim:	TP
		Claim No:	0693378218SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC4957H	Engine No:	21752568
Make & Model:	YUTONG ZK6100H, 6.7 D (M)	Chassis No:	L2YTBTD6871016897
Reg. Date:	14/03/2008 (Man. Year: 2007)	Odometer:	812617 km
Colour:	Grey		
Engine Capacity:	6693 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	ANNAITE 6 mm	Rear Left Side:	ANNAITE 6/6 mm
Front Right Side:	ANNAITE 6 mm	Rear Right Side:	ANNAITE 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,476.00	11,081.00	20,395.00	64.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,130.00	3,440.00	2,690.00	43.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,606.00	14,521.00	23,085.00	61.39
Approved Total (Overridden) (S\$)		11,500.00		
(S\$)	37,606.00	11,500.00	26,106.00	69.42
+ GST 7.00/7.00% (S\$)	2,632.42	805.00	1,827.42	69.42
Nett Amount (S\$)	40,238.42	12,305.00	27,933.42	69.42
+ Loss of Use (5.0 x S\$150.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,057.00		
Global Sum Settlement (S\$)		13,050.00		

INSPECTION

Date of Assignment:	01/12/2021	
Date Inspected:	01/12/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR ENGINE HOOD	Not Necessary	3,850.00 F	*- FL
2	1		*REAR ENGINE HOOD EMBLEM	Not Necessary	250.00 F	*- FL
3	1		*REAR ENGINE HOOD OUTER HANDLE	Not Necessary	292.00 F	*- FL
4	1		*REAR ENGINE HOOD DAMPER STAY	Not Necessary	345.00 F	*- FL
5	1		*REAR ENGINE HOOD LOWER REFLECTOR	Cracked	1,500.00 F	*1,120.00 FL
6	1		*REAR LICENCE PLATE LAMP	Cracked	105.00 F	*90.00 FL
7	1		*REAR BUMPER	Distorted	3,600.00 F	*2,500.00 FL
8	1		*REAR BUMPER BEAM	Bent	1,200.00 F	*900.00 FL
9	1		*REAR BUMPER INNER BEAM	No such part	1,100.00 F	*- FL
10	2		*REAR TAILLAMPS	Not Necessary	1,990.00 F	*- FL
11	2		*REAR TAILLAMP HOUSING PANELS	Cracked / Dented	7,000.00 F	*5,600.00 FL
12	1		*AIRCON COMPRESSOR	Not Necessary	3,624.00 F	*- FL
13	1		*AIRCON COMPRESSOR BELT	Not Necessary	205.00 F	*- FL
14	1		*AIRCON COMPRESSOR TENSIONER BEARING	Not Necessary	850.00 F	*- FL
15	1		*REAR AIR CON TENSIONER BEARING BRACKET	Not Necessary	350.00 F	*- FL
16	1		*REAR CENTRE CROSS MEMBER	Bent	2,450.00 F	*2,080.00 FL
17	1		*REAR LOWER MEMBER BRACKET	Repair	650.00 F	*- FL
18	1		*REAR EXHAUST	Repair	1,800.00 F	*- FL
19	1		*REAR EXHAUST MOUNTING	Not Necessary	50.00 F	*- FL
20	1		*REAR LICENCE PLATE	Bent	50.00 FS	*20.00 FS
21	1		*SET REAR REVERSE BUZZLE	Not Necessary	200.00 FS	*- FS
22	1		*REAR 60KM/H STICKER	Not Necessary	15.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	31,476.00	12,310.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,229.00
Total Parts (\$\$)	31,476.00	11,081.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO RESET & REPOGRAMME ENGLNE DIAGNOSIS TEST	New	200.00	80.00
4	TO REMOVE AND REPLACED AIR CON COMPRESSOR & REFILL GAS	New	200.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	3,800.00	2,200.00
6	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
Gross Labour Cost (S\$)			6,130.00	3,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >