

ASS. REC BY: Marcus

REF:

CCG/AIG21012206/4rs3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 4957H
at Workshop m/s
of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

days

Res.: Yes or No

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

B1 involved on 13-3-2023
No SG car met

22/3/22 4/5 \$11,500 informed Alan

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/Q / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.): (\$

HSCAD 2019

not Authorized
all
1/12/21
2/5# 11500/
5 days.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: PC 4957H

1PC	REAR ENGINE HOOD	11	\$3,850.00	X
1SET	REAR ENGINE HOOD EMBLEM	11	\$250.00	X
1PC	REAR ENGINE HOOD OUTER HANDLE	11	\$292.00	X
1PC	REAR ENGINE HOOD DAMPER STAY	11	\$345.00	X
1PC	REAR ENGINE HOOD LOWER REFLECTOR	CR2 1120	\$1,500.00	X
1PC	REAR LICENCE PLATE LAMP	CR2 90	\$105.00	/
1PC	REAR BUMPER FIBREGLASS	Dis 2500	\$3,600.00	/
1PC	REAR BUMPER BEAM	Bent 900	\$1,200.00	/
1PC	REAR BUMPER INNER BEAM	NS	\$1,100.00	X
2PCS	REAR TAILLAMPS @ \$995.00	11	\$1,990.00	X
2PCS	REAR TAILLAMP HOUSING PANELS @ \$3500.00	CR2/27 2800x2=5600	\$7,000.00	/
1PC	AIR CON COMPRESSOR	11	\$3,624.00	X
1PC	AIR CON COMPRESSOR BELT	11	\$205.00	X
1PC	AIR CON COMPRESSOR TENSIONER BEARING	11	\$850.00	X
1PC	REAR AIR CON TENSIONER BEARING BRACKET	11	\$350.00	X
1PC	REAR CENTRE CROSS MEMBER	Bent 2060	\$2,450.00	/
1PC	REAR LOWER MEMBER BRACKET	R	\$650.00	X
1PC	REAR EXHAUST	R	\$1,800.00	X
1PC	REAR EXHAUST MOUNTING	11	\$50.00	X
			\$31,211.00	

(102)

S.NETT

1PC	REAR LICENCE PLATE	Bent	\$50.00	20
1SET	REAR REVERSE BUZZLE	11	\$200.00	X
1PC	REAR 60km/h STICKER	11	\$15.00	X
	TO CHECK WIRING		\$50.00	30
	TO SPRAY RUST PROOFING		\$80.00	30
	TO RESET & REPROGRAMME ENGLNE DIAGNOSIS TEST		\$200.00	80
	TO REMOVE AND REPLACED AIR CON COMPRESSOR & REFILL GAS		\$200.00	X
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$3,800.00	2200
	TO PUTTY & SPRAY PAINTING		\$1,800.00	1100
			\$37,606.00	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12290
117
11061
3460