



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 30.11.2021
Emailed : 17.12.2021, 5pm
Date survey : 02.12.2021

VEHICLE NO : SFT 7710 L
MODEL : KIA CERATO 1.6 A EX
WIP : 43264

Material	:	\$	1,175.20
Labour	:	\$	3,380.00
Sub-Total	:	\$	4,555.20
	:		-
Less Excess	:	\$	600.00
Total	:	\$	3,955.20
GST 7%	:	\$	276.86
Grand Total	:	\$	4,232.06
Finalise By/Date	:	LOI / 17/12/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 02/12/2021	Cust No/Name	/TAN BOON SOO
	Reg No/Reg Date	SFT7710L / 07/12/2018
	Date In/Mileage	01/12/2021/ 38387
	Chassis/Package	KNAF3416MK5022966 /KC17P
	Engine No	G4FGJH712643
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	17/12/2021/ 09:38	BLK	260 / AiTing	43264			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE LH REAR DOOR, REPAIR REAR BUMPER, LH REAR FENDER, LH SIDE SILL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1000.00
E PNT98000 RESPRAY ON REAR BUMPER, LH REAR FENDER, LH REAR DOOR, LH SIDE SILL, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1400.00
E PNT88000 TRANSFER LH REAR DOOR ATTACHMENTS TO NEW PANEL								✓ 120.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 40.00
M SUNDRY APPLY SEALANT ON AFFECTED AREAS								✓ 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY TRANSFER LH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								✓ 30.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								✓ 120.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR								✓ 80.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY LH REAR SPORTS RIM								✓ 380.00
X EXC INSURANCE EXCESS								-600.00
X PANEL ASSY-REAR DOOR,LH					1.00	✓ 1377.00	20.00	1101.60
X MOULDING ASSY-RR DR FRAME,LH					1.00	✓ 44.00	20.00	35.20
X FILM-ANTI CHIPPG LH					1.00	✓ 27.00	20.00	21.60

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 02/12/2021	Cust No/Name	/TAN BOON SOO
	Reg No/Reg Date	SFT7710L / 07/12/2018
	Date In/Mileage	01/12/2021/ 38387
	Chassis/Package	KNAF3416MK5022966 /KC17P
	Engine No	G4FGJH712643
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/12/2021/ 09:38	BLK	260 / AiTing	43264

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BLACK TAPE-RR DR FR,LH → Supp.	1.00	13.00	20.00	10.40
X BLACK TAPE-RR DR FRAME RR OTR, → Supp.	1.00	8.00	20.00	6.40
Z TEXT				
AIG OD CLAIM				
DOA : 30.11.21				
SURVEYOR STEVE-LKK 02.12.21				
POLICY NO : 1800145347-01 REPAIR 05 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	1,175.20	Nett	3,955.20
Labour	2,870.00	7% GST on	276.86
Standard Menu	0.00		
Specialist Job	380.00	Total Payable	4,232.06
Diagnostics Job	0.00		
Sundry/Others	-470.00		
Total(w/o GST)	3,955.20		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SFT 7710 L**

<u>Materials</u>		<u>Cost (\$)</u>
1	Black tape-RR dr fr, LH	13.00
2	Black tape-RR dr frame RR otr	8.00

Total		21.00
Less 20% discount		4.20

Total after discount		16.80
7% GST		1.18

Grand total		<u>17.98</u>

Thank You.

Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SFT 7710L

WIP: 43264

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	LH Back Top	? / SUPP			77511 m 6000
2	LH Top	? / SUPP			77513 m 6000
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
3/12	

MODEL: Cerato 1.6

SURVEYOR: Steve - 666

Work Order: R001590
 License: sft 7710 I
 Technician: 810119 kfsan
 Mileage: 38388
 Date: 8.12.21 14:06

Kia : Cerato/Forte : 2019- (BD/BDm) : without Independent Rear Suspension : Rest of World

Front : Left

Actual	Before	Specified Range
-0°24'	-0°24'	-0°53' 0°07'
4°10'	4°10'	4°00' 5°00'
0°01'	0°01'	-0°03' 0°09'
9°27'*	9°27'*	13°30' 14°30'
9°03'*	9°03'*	12°37' 14°37'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°52'	-0°52'	-0°53' 0°07'
4°57'	4°57'	4°00' 5°00'
0°00'	0°00'	-0°03' 0°09'
15°15'*	15°14'*	13°30' 14°30'
14°22'	14°22'	12°37' 14°37'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°28'	0°28'	
-0°47'	-0°47'	
-5°47'	-5°47'	
0°01'	0°01'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°00'	-1°00'	-1°42' -0°42'
0°03'	0°03'	-0°02' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°36'	-1°36'	-1°42' -0°42'
0°09'	0°09'	-0°02' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°36'	0°36'	
0°12'	0°12'	-0°04' 0°32'
-0°03'	-0°03'	



* This value is not within specification. Tire wear, handling and safety problems may result.



Fault Code Searching

Rescan

Save



9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0259

VCI Ver.

02.63

ECU Ver.

M-E-K-01-00-0199

OS Ver.

Android 10