12/15/21, 9:33 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012212/ETY3N2

15/12/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00123362102

Claimant Vehicle

SJS9163K

Insured Vehicle GBH9187U No:

Date of Loss:

No:

Nature of Claim: TP

Claim

30/11/2021

SNM21D206942/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJS9163K Reg No:

Make & Model: SUZUKI SWIFT, 1.2 XG (A) Engine No: K12B1065258 Reg. Date: 15/09/2009 (Man. Year: 2008) Chassis No: ZC71S437188 Colour: Red Odometer: 112055 km

Engine Capacity: 1242 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: Nο

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15 Front Left Side: Rear Left Side: Dunlop 4 mm Dunlop 4 mm Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	297.15	237.15	60.00	20.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	560.00	1,230.00	68.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	2,087.15	797.15	1,290.00	61.81
Approved Total (Overridden) (S	S\$)	650.00		
(\$	2,087.15	650.00	1,437.15	68.86
+ GST 7.00/7.00% (S	5\$) 146.10	45.50	100.60	68.86
Nett Amount (S	2,233.25	695.50	1,537.75	68.86

INSPECTION

Date Inspected:

Date of Assignment: 01/12/2021

> Wah Hong Motors & Credit Pte Ltd (HQ) 07/12/2021 Inspected At:

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Dec 2021)

Parts: 144 SUZUKI SWIFT 1.2 XG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJS9163K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	259.00 FL	*259.00 FL
2	1		*FRONT FENDER SIGNAL LAMP LH	Broken	20.00 FL	*20.00 FL
3	1		*FRONT BUMPER (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*FRONT DOOR LH (NPA)	Not Necessary	0.00 FL	*- FL
5	1		*FRONT BUMPER CLIPS	Not Necessary	35.00 FS	*- FS
6	1		*FRONT FENDER SHIELD CLIPS	Not Necessary	25.00 FS	*- FS
F=Fra	ınchise	part. S=SpcNe	ett. L=ListItemDisc.	-		
				Sub Total (S\$)	339.00	279.00
			- List Item Discount o	on L Items 15.00/15.00% (S\$)	41.85	41.85
				Total Parts (S\$)	297.15	237.15
			Report was unsubmitted	I during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	800.00	200.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	800.00	200.00
3	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	30.00	30.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	30.00	20.00
5	CHECK AND WHEEL COMPUTERIZE ALIGNMENT	New	80.00	60.00
6	TO REMOVE AND REFIXS FRONT TYRE AND WHEEL BALANCING IN ORDER TO FRONT RIM LH	New	50.00	50.00
	Gross Labour Cost (S\$)		1,790.00	560.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >