



Your Ref : 21/21/21/VP05/025202

Date: 10<sup>th</sup> Dec 2021

Our Ref : CS/LPC21012214/Ktf3e2

**M/s Lonpac Insurance Bhd**

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKJ 6623E  
ACCIDENT ON 27/11/2021**

Instruction was received to inspect the vehicle Reg. No. SKJ 6623E. The inspection was conducted on 02/12/2021 at the premises of M/s S & H Motor Pte Ltd, 160 Sin Ming Drive #07-02 Sin Ming Autocity, Singapore 575722.

The following vehicle information was recorded:

Registration Number	: SKJ 6623E
Make/Model	: Audi A6 2.0 TFSI MU
Year of Registration	: 2013
Body Colour	: Metallic Dark Grey
Chassis Number	: WAUZZZ4G4DN077016
Engine Capacity	: 1984 cc

The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 45,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 30,889.00)
Nett Liability	<u>S\$ 14,111.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG  
Licensed Appraiser



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.