

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012215/ATY3S2**Date:** 19/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00101102103

Claimant Vehicle No : SNB3324U **Insured Vehicle No :** GBD3464E

Date of Loss: 30/11/2021 Nature of Claim: TP Claim No: SNM21D206941/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB3324U**

Make & Model: BMW 340I, 3.0 M SPORT AUTO (A) Engine No: HIDDEN

Reg. Date: 01/12/2015 (Man. Year: 2015) Chassis No: WBA8B32040K467306

Colour: Red Odometer: 93261 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 245/35 R19

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,541.73	8,140.23	20,401.50	71.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	1,210.00	2,840.00	70.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,591.73	9,350.23	23,241.50	71.31
Approved Total (Overridden) (\$\$)		7,450.00		
Nett Amount (\$\$)	32,591.73	7,450.00	25,141.73	77.14

INSPECTION

Date of Assignment: 01/12/2021

Date Inspected: 02/12/2021 Inspected At: PROVI AUTOWORKS PTE LTD (HQ)
8 Kaki Bukit Avenue 4, #02-24 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2022)
Parts:	143	BMW 340I 3.0 M SPORT AUTO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB3324U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,141.00 FL	*1,680.00 FL
2	1		*FRONT BUMPER TOP RUBBER	Not Necessary	178.00 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	O/s Damaged	220.00 FL	*110.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	744.00 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Cracked	258.00 FL	*168.00 FL
6	1		*FRONT BUMPER SIDE AIR ARCH RH	Deformed	355.40 FL	*230.00 FL
7	1		*FRONT BUMPER UNDER SIDE COVER	Deformed	355.40 FL	*235.00 FL
8	1		*FRONT BUMPER UNDER CENTER COVER	Not Necessary	489.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP RH	Cracked	498.00 FL	*308.00 FL
10	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	189.00 FL	*- FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	248.00 FL	*- FL
12	1		*FRONT GRILLE RH	Not Necessary	568.00 FL	*- FL
13	1		*FRONT GRILLE AIR ARCH INNER	Not Necessary	652.00 FL	*- FL
14	2		*HEAD LAMP	O/s Cracked	7,796.00 FL	*3,450.00 FL
15	2		*HEAD LAMP BOTTOM BRACKET	Not Necessary	558.80 FL	*- FL
16	1		*WATER COOLER	Not Necessary	939.00 FL	*- FL
17	1		*WATER COOLER AIR ARCH	Not Necessary	178.00 FL	*- FL
18	1		*WATER COOLER BRACKET	Torn	128.00 FL	*128.00 FL
19	1		*FRONT FENDER RH	Dented	969.70 FL	*969.70 FL
20	1		*FRONT FENDER EMBLEM (M)	Necessary	121.00 FL	*121.00 FL
21	1		*FRONT FENDER INNER SHIELD RH	Torn	330.50 FL	*245.00 FL
22	1		*SIDE SKIRT RH	Not Necessary	842.00 FL	*- FL
23	1		*FRONT ABSORBER RH	Not Necessary	753.70 FL	*- FL
24	1		*FRONT LOWER ARM RH	Not Necessary	521.00 FL	*- FL
25	1		*FRONT CONTROL ARM RH	Not Necessary	689.00 FL	*- FL
26	1		*FRONT KNUCKLE ARM RH	Not Necessary	754.00 FL	*- FL
27	1		*FRONT WHEEL BEARING RH	Not Necessary	555.20 FL	*- FL
28	1		*FRONT ANTI ROLL BAR LINK RH	Not Necessary	215.00 FL	*- FL
29	1		*STEERING RACK AND PINION	Not Necessary	3,086.70 FL	*- FL
30	1		*SET FRONT BUMPER CLIP	Necessary	75.00 FS	*30.00 FS
31	1		*SET FRONT BUMPER GRILLE	Not Necessary	500.00 FS	*- FS
32	1		*SET RADIATOR GRILLE CLIP	Not Necessary	40.00 FS	*- FS
33	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	90.00 FS	*30.00 FS
34	1		*COOLANT	Not Necessary	120.00 FS	*- FS
35	1		*FRONT RIM RH	Cut	3,000.00 FS	*1,200.00 FS
36	1		*FRONT TYRE RH	Not Necessary	600.00 FS	*- FS
37	1		*SIDE SKIRT CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	29,808.40	8,904.70
- List Item Discount on L Items 5.00/10.00% (\$)	1,266.67	764.47
Total Parts (\$)	28,541.73	8,140.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS.	New	1,200.00	600.00
2	TO SPRAY PAINT AFFECTED AREA.	New	1,200.00	500.00
3	WIRING, BULB CHECKING.	New	150.00	30.00
4	REFOCUS HEADLAMP BEAM AND CODING AND PROGRAMMING.	New	600.00	0.00
5	TO REMOVE AND INSTALL FRONT UNDER CARRIAGE.	New	800.00	0.00
6	TO CHECK FOUR WHEEL ALIGNMENT.	New	100.00	80.00
Gross Labour Cost (S\$)			4,050.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >