

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012226/UPA3Q2**Date:** 18/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900169054
Claimant Vehicle No :	GBC7716H	Insured Vehicle No :	YP4770D
Date of Loss:	29/11/2021	Nature of Claim:	TP
		Claim No:	0136209250SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC7716H	Engine No:	198A30006975032
Make & Model:	FIAT DOBLO, 1.6 D CARGO MJ (M)	Chassis No:	ZFA26300009254362
Reg. Date:	25/10/2013 (Man. Year: 2013)	Odometer:	155038 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Transway 6 mm	Rear Left Side:	Transway 6 mm
Front Right Side:	Transway 6 mm	Rear Right Side:	Transway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,454.40	3,627.15	2,827.25	43.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	900.00	610.00	40.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,964.40	4,527.15	3,437.25	43.16
Approved Total (Overridden) (S\$)		3,600.00		
Nett Amount (S\$)	7,964.40	3,600.00	4,364.40	54.80
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,902.00		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment:	02/12/2021	
Date Inspected:	02/12/2021 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,170.00 F	*1,067.55 FL
2	1		*FRONT BONNET INNER LOCK	Serviceable	145.00 F	*- FL
3	2		*FRONT HEAD LAMP	Holder Cracked	1,724.80 F	*1,570.60 FL
4	1		*FRONT BUMPER	Dented / Torn	1,245.50 F	*864.07 FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	68.00 F	*50.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	752.00 F	*- FL
7	1		*FRONT BUMPER SPONGE	Serviceable	117.60 F	*- FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	685.00 FS	*- FS
9	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	65.00 F	*- FL
10	1		*FRONT GRILLE	Cut	317.80 F	*317.80 FL
11	1		*FRONT GRILLE FIAT LOGO MOTIF	Scratched	115.70 F	*115.70 FL
12	1		*FRONT NUMBER PLATE AND BASE	Bent	48.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,454.40	4,025.72
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	398.57
Total Parts (\$)	6,454.40	3,627.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	400.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	600.00	450.00
4	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	30.00
Gross Labour Cost (\$\$)			1,510.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >