

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012228/UGA3**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800072118-03
Claimant Vehicle No :	FBP6918E	Insured Vehicle No :	SMA81G
Date of Loss:	27/11/2021	Nature of Claim:	TP
		Claim No:	2190932915SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP6918E	Engine No:	G3H6E0013884
Make & Model:	YAMAHA NMAX155, 155cc	Chassis No:	MH3SG431000011161
Reg. Date:	23/05/2019 (Man. Year: 2019)	Odometer:	110285 km
Colour:	Grey		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	130/70-13
Front Left Side:	Timsun 7 mm	Rear Left Side:	Timsun 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,867.50	465.00	1,402.50	75.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	185.00	495.00	72.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,547.50	650.00	1,897.50	74.48
Approved Total (Overridden) (S\$)		500.00		
(S\$)	2,547.50	500.00	2,047.50	80.37
+ GST 7.00/7.00% (S\$)	178.33	35.00	143.33	80.37
Nett Amount (S\$)	2,725.83	535.00	2,190.83	80.37
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		597.00		

INSPECTION

Date of Assignment:	02/12/2021	
Date Inspected:	02/12/2021	Inspected At: Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELLY PAN	Not Necessary	35.00 F	*- FL
2	1		*BOARD FOOTREST LH	Not Necessary	55.00 F	*- FL
3	1		*BOX FILTER AIR OUTER	Grazed	18.00 F	*18.00 FL
4	1		*BOX FILTER AIR OUTER FRONT	Not Necessary	10.00 F	*- FL
5	2		*BUSH ENGINE	Not Necessary	16.00 F	*- FL
6	5		*CLIP NUT SPRING	Not Necessary	7.50 F	*- FL
7	1		*COVER CLUTCH OUTER	Not Necessary	66.00 F	*- FL
8	1		*COVER FRONT (GREY)	Not Necessary	35.00 F	*- FL
9	1		*COVER SIDE LH (MATTE BLACK)	Not Necessary	38.00 F	*- FL
10	1		*COVER SIDE LOWER LH (BLUE)	Not Necessary	21.00 F	*- FL
11	1		*COVER SIDE REAR LH (BLUE)	Not Necessary	28.00 F	*- FL
12	1		*COVER SIDE REAR RH (GREY)	Not Necessary	28.00 F	*- FL
13	1		*COWLING FRONT LH (BLUE)	Not Necessary	32.00 F	*- FL
14	1		*DAMPER PLATE	Not Necessary	3.00 F	*- FL
15	2		*EMBLEM (YAMAHA) LOGO	Not Necessary	28.00 F	*- FL
16	1		*ENGINE BRACKE COMP	Not Necessary	68.00 F	*- FL
17	1		*FOOTREST REAR ASSY 1 LH	Not Necessary	32.00 F	*- FL
18	1		*HEADLAMP ASSY	Not Necessary	299.00 F	*- FL
19	4		*HOOK COVER SIDE	Not Necessary	6.00 F	*- FL
20	1		*LAMP SIGNAL FRONT LH	Not Necessary	34.00 F	*- FL
21	1		*LAMP TAIL ASSY	Cracked	223.00 F	*223.00 FL
22	1		*LEVER BRAKE LH	Not Necessary	18.00 F	*- FL
23	1		*MIRROR LH	Not Necessary	35.00 F	*- FL
24	1		*MUDGUARD FRONT (GREY)	Not Necessary	45.00 F	*- FL
25	1		*MUDGUARD REAR	Distorted	49.00 F	*49.00 FL
26	1		*PANEL 1 (MATTE BLACK) LH	Not Necessary	21.00 F	*- FL
27	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	28.00 FS	*15.00 FS
28	2		*REFLECTOR REAR	Not Necessary	9.00 F	*- FL
29	12		*RIVET	Not Necessary	36.00 F	*- FL
30	4		*SCREW (VISOR)	Not Necessary	12.00 F	*- FL
31	1		*SEAT HANDLE (BLACK) (CUT)	Not Consistent With The Impact	135.00 F	*- FL
32	1		*SHAFT PIVOT	Not Necessary	12.00 F	*- FL
33	2		*SHOCK ABSORBER REAR	Bent / Twisted	210.00 F	*210.00 FL
34	1		*STAND MAIN	Not Necessary	63.00 F	*- FL
35	1		*STICKER (MCDONALD) COVER SIDE	Not Necessary	18.00 F	*- FL
36	1		*STICKER (MCDONALDS) SIDE COVER /WINDSHIELD	Not Necessary	16.00 F	*- FL
37	1		*STICKER NUMBER PLATE FRONT (BLACK)	Not Necessary	15.00 F	*- FL
38	1		*STOPPER ,MAIN STAND	Not Necessary	7.00 F	*- FL
39	1		*WINDSHIELD	Not Necessary	56.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,867.50	515.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	50.00
Total Parts (\$)	1,867.50	465.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES	New	50.00	35.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	630.00	150.00
Gross Labour Cost (\$)			680.00	185.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >