

ASSESSMENT REPORT FOR VEHICLE NO. SKZ 28 D

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT RH HEADLAMP <i>3805.60</i>	Cracked	3,805.60	3,805.60
1	FRONT RH HEADLAMP GARNISH	Cut	<i>Sm</i> 82.00	82.00 X
1	FRONT GRILLE ASSY	Cracked	532.00	532.00
1	FRONT BUMPER <i>845.10</i>	Cracked	1,460.00	1,460.00
2	FRONT BUMPER SIDE RETAINER L/R	Bent	168.00	168.00
1	FRONT BUMPER RH FOGLAMP	Cracked	248.20	248.20
1	FRONT BUMPER RH FOGLAMP GARNISH	Cracked	153.20	153.20
1	FRONT BUMPER RH FOGLAMP BRACKET	Bent	78.00	78.00
1	FRONT BUMPER CHROME GARNISH	Cracked	335.20	335.20
1	FRONT BUMPER INNER SPONGE	Cracked	<i>Sm</i> 110.10	110.10 X
1	FRONT BUMPER LOWER CENTER GRILLE	Cracked	161.80	161.80
1	FRONT BUMPER PARKING SENSOR (ORIGINAL)	Cracked	232.00	232.00
1	FRONT BUMPER PARKING SENSOR HOLDER	Necessary	15.00	15.00
1	FRONT BUMPER REINFORCEMENT	Repair	332.00	-
1	FRONT BUMPER LOWER UNDER COVER	Cracked	211.00	<i>Sm</i> 211.00 X
1	FRONT RH FENDER	Repair	636.48	-
1	FRONT RH FENDER INNER SHIELD	Cut	203.92	<i>Sm</i> 203.92 X
1	FRONT RH FENDER BRACKET	Repair	95.47	-
1	FRONT RH DOOR	Repair	1,451.97	-
			<u>10,311.94</u>	<u>7,796.02</u>
Less 25% discount			<u>2,577.99</u>	<u>1,949.01</u>
Parts Total:			<u>7,733.96</u>	<u>5,847.02</u>

AEON AUTO CONSULTANTS LLP
 50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
 Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com
 Reg. No. LL0701273L (registered with limited liability)

ASSESSMENT REPORT FOR VEHICLE NO. SKZ 28 D

SPECIAL NETT ITEMS

1	FRONT GRILLE CLIPS - SET	Necessary	30.00	30.00
1	FRONT RH HEADLAMP CLIPS - SET	Necessary	30.00	30.00
1	FRONT BUMPER CLIPS - SET	Necessary	30.00	30.00
1	FRONT RH FENDER INNER SHIELD CLIPS & PIN - SET	Necessary	30.00	30.00
Special Nett Total :			120.00	120.00

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment	
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	140.00	120.00	301
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	nn. 1,200.00	1,000.00	X
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	1,000.00	600k
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	100.00	80.00	✓
Labour Total :		2,640.00	2,200.00	
TOTAL (PARTS & LABOUR) \$		10,493.96	8,167.02	

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$6,800.00 (SINGAPORE DOLLARS SIX THOUSAND EIGHT HUNDRED ONLY)



Amas Ong
Automobile Assessor

4 days