

Qty

LKK Auto Consultants Pte Ltd

Condition

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

Estimate By

Workshop (\$))

Our Adjusted

(\$)

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 6116E

Description of Parts

REPLACEMENT OF PARTS

RECOMMENDED COST OF LUMP SUM REPAIRS			1,600.0
GRAND TOTAL		3,724.15	1,976.9
		1,770.00	740.0
TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.	NOT NECESSARY	50.00	
TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		800.00	400.0
TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS. TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR FENDER LH AND RR END PANEL.		800.00	300.0
TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK REAR ELECTRICAL WIRING SYSTEM. TO TRANSFER REAR PDC SENSORS TO NEW BUMPER. (INCLUDE RESET / REPROGRAM CONTROL UNIT)		120.00	
LABOUR		120.00	40.0
		1,954.15	1,236.9
LESS 5% DISCOUNT		-102.85	-65.1
RR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	
RR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	
RR BUMPER SIDE GUIDE LH	DENTED / CRACKED	92.00	92.0
RR BUMPER PDC SENSOR LH	SERVICEABLE	363.00	
RR BUMPER	DENTED / DEFORMED	1,210.00	1,210.0
TAILLAMP LH	SERVICEABLE		

Report Ref No. CS1/III21012232/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.