

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



1/33: Inspection Photo



2/33: Inspection Photo




3/33: Inspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



4/33: Inspection Photo



5/33: Inspection Photo



6/33: Inspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



7/33: Inspection Photo



8/33: Inspection Photo



9/33: Inspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



10/33: Inspection Photo



11/33: Inspection Photo



12/33: Inspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



13/33: Inspection Photo



14/33: Inspection Photo



15/33: Inspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



16/33: Inspection Photo



17/33: Inspection Photo



18/33: Inspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



19/33: Inspection Photo



20/33: Inspection Photo



21/33: Reinspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



22/33: Reinspection Photo



23/33: Reinspection Photo



24/33: Reinspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



25/33: Reinspection Photo



26/33: Reinspection Photo



27/33: Reinspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



28/33: Reinspection Photo



29/33: Reinspection Photo



30/33: Reinspection Photo

SJZ6116E [SMW6410K] - Submitted by: JP Knights Pte Ltd (HQ)



31/33: Reinspection Photo



32/33: Reinspection Photo



33/33: Reinspection Photo