12/9/21, 2:10 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21012234/VTF3N2

Date: 09/12/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MU012019

Claimant Vehicle Outcomes Company

No: SHC653E Insured Vehicle No: SJD8090Y

Date of Loss: 01/12/2021 Nature of Claim: TP Claim No: M2105572

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC653E

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU298121

Reg. Date: 02/07/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU164728

Colour: Yellow Odometer: 299369 km

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,421.36	813.60	607.76	42.76
Miscellaneous Items		11.00	11.00	0.00	0.00
Labour		820.00	620.00	200.00	24.39
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Gros	ss Total (S\$)	2,252.36	1,444.60	807.76	35.86
+ GST 7.0	0/7.00% (S\$)	157.67	101.12	56.55	35.87
Nett /	Amount (S\$)	2,410.03	1,545.72	864.31	35.86

INSPECTION

Date of Assignment: 02/12/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 02/12/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/9/21, 2:10 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Dec 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC653E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	-	*- FL
2	1		*REAR BUMPER CENTRE MOULDING	Scratched	451.25 FL	-	*451.25 FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
4	1		*REAR BUMPER TOW COVER	Serviceable	98.80 FL	-	*- FL
5	1		*REVERSE SENSORS	Cut	180.00 F	-	*180.00 FS
6	1		*REAR BUMPER FOGLAMP	Serviceable	201.50 FL	-	*- FL
7	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	Necessary	200.00 F	-	*200.00 FS
8	1		*REAR NO.PLATE WITH TRIM COVER	Scratched	55.00 F	-	*55.00 FS
F=Fra	ınchise	part. S=Spc	Nett. L=ListItemDisc.				
				Sub Total (S\$)	1,667.95	908.25	
			- List Item Discount on L Items 20.	00/20.00% (S\$)	246.59	94.65	
			т	otal Parts (S\$)	1,421.36		813.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty I	Particulars		Repairer's	Amount
Miscellane	ous Items			
1 1 (OD/TP Case (Insurer)		11.00	11.00
		Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	20.00
		Gross Labour Cost (S\$)	820.00	620.00
	Re	eport was unsubmitted during this print-out.		

< END OF ESTIMATES >