

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012237/KTY3N2**Date:** 28/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00191922100
Claimant Vehicle No :	SMW3013T	Insured Vehicle No :	SNB8649A
Date of Loss:	29/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206885/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW3013T	Engine No:	A25A0A10143
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	JTNB23HK103070515
Reg. Date:	12/11/2020 (Man. Year: 2020)	Odometer:	23377 km
Colour:	Metallic Silver		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,144.75	3,179.70	7,965.05	71.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,200.00	1,500.00	55.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,844.75	4,379.70	9,465.05	68.37
Approved Total (Overridden) (\$\$)		3,400.00		
(\$\$)	13,844.75	3,400.00	10,444.75	75.44
+ GST 7.00/7.00% (\$\$)	969.13	238.00	731.13	75.44
Nett Amount (\$\$)	14,813.88	3,638.00	11,175.88	75.44

INSPECTION

Date of Assignment:	02/12/2021	
Date Inspected:	02/12/2021	Inspected At: Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2022)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW3013T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,513.00 FL	*1,031.00 FL
2	1		*BOOTLID INNER TRIM	Serviceable	181.00 FL	*- FL
3	2		*BOOTLID HINGE	Repair	134.00 FL	*- FL
4	1		*BOOTLID LOCK	Repair	359.00 FL	*- FL
5	1		*BOOTLID LOCK STRIKER	Repair	65.00 FL	*- FL
6	1		*BOOTLID RELEASE ANTENNA	Serviceable	324.00 FL	*- FL
7	1		*BOOTLID RELEASE CABLE	Serviceable	153.00 FL	*- FL
8	1		*BOOTLID WEATHERSTRIP	Serviceable	185.00 FL	*- FL
9	2		*LICENCE PLATE LAMP	Serviceable	184.00 FL	*- FL
10	1		*BOOTLID OUTER GARNISH	Serviceable	277.00 FL	*- FL
11	2		*BOOTLID HINGE GARNISH	Serviceable	98.00 FL	*- FL
12	1		*BOOTLID TOYOTA LOGO	Necessary	113.00 FL	*113.00 FL
13	1		*BOOTLID OUTER GARNISH CAMRY EMBLEM	Not Necessary	87.00 FL	*- FL
14	1		*BOOTLID HYBRID EMBLEM	Necessary	92.00 FL	*92.00 FL
15	1		*REAR BUMPER	Buckled	2,375.00 FL	*573.00 FL
16	1		*REAR BUMPER SIDE RETAINER	N/s Distorted	374.00 FL	*187.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	776.00 FL	*510.90 FL
18	1		*REAR BUMPER LOWER DIFFUSER	Serviceable	688.00 FL	*- FL
19	1		*TAILLAMP N/S	Cracked	989.00 FL	*605.70 FL
20	1		*TAILLAMP INNER GARNISH N/S	Serviceable	137.00 FL	*- FL
21	1		*TAILLAMP PANEL N/S	Repair	147.00 FL	*- FL
22	1		*TAILLAMP LOWER BRACKET N/S	Serviceable	65.00 FL	*- FL
23	1		*END PANEL	Repair	732.00 FL	*- FL
24	1		*END PANEL TOP GARNISH	Serviceable	164.00 FL	*- FL
25	2		*REAR BUMPER REFLECTOR	Serviceable	526.00 FL	*- FL
26	1		*REAR LICENCE PLATE & FRAME	Serviceable	55.00 FS	*- FS
27	1		*REVERSE CAMERA	Serviceable	550.00 FS	*- FS
28	1		*REVERSE SENSOR (2 Pcs)	Shorted (1 Pc only)	760.00 FS	*210.00 FS
29	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	55.00 FS	*- FS
30	12		*REAR BUMPER CLIPS	Necessary	66.00 FS	*66.00 FS
31	6		*TAILLAMP CLIPS	Not Necessary	33.00 FS	*- FS
32	6		*BOOTLID LAMP CLIPS	Not Necessary	33.00 FS	*- FS
33	1		*END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
34	1		*END PANEL TOP GARNISH CLIPS	Not Necessary	44.00 FS	*- FS
35	8		*SUNDRIES	Not Necessary	50.00 FS	*- FS
36	1		*BOOTLID LAMP N/S	Cracked	759.00 FL	*759.00 FL
37	1		*BOOTLID LAMP SPONGE SEAL N/S	Serviceable	8.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,271.00** **4,147.60**
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,126.25 967.90

Total Parts (\$\$) **11,144.75** **3,179.70**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	500.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	20.00
3	TO REMOVE,REFIT BOOTLID COMPONENTS AND REPLACE BOOTLID,CHECK AND RE-ADJUST CLOSE GAP,ALIGNMENT AND WATER SEEPAGE	New	100.00	50.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,200.00	600.00
5	TO UNDERCOAT ALL AFFECTED PORTIONS AFTER REPAIR	New	150.00	30.00
Gross Labour Cost (\$\$)			2,700.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >