

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21012244/UTF3N2
Date: 03/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070089838
Claimant Vehicle No :	XE1003A	Insured Vehicle No :	GBB2719M
Date of Loss:	18/11/2021	Nature of Claim:	TP
		Claim No:	3949747714SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE1003A	Engine No:	50539592123964
Make & Model:	MAN TGS 18.320, 10.5 D 4X2 BLS (M)	Chassis No:	WMA49SZZ0FM662489
Reg. Date:	14/09/2015 (Man. Year: 2014)	Odometer:	544403 km
Colour:	White		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5(D/D)
Front Left Side:	HILO 6 mm	Rear Left Side:	HILO 6/66/6 mm
Front Right Side:	HILO 6 mm	Rear Right Side:	HILO 6/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,422.55	7,448.19	2,974.36	28.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,580.00	2,120.00	57.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,122.55	9,028.19	5,094.36	36.07
Approved Total (Overridden) (S\$)		7,200.00		

(S\$)	14,122.55	7,200.00	6,922.55	49.02
+ GST 7.00/7.00% (S\$)	988.58	504.00	484.58	49.02
Nett Amount (S\$)	15,111.13	7,704.00	7,407.13	49.02

INSPECTION

Date of Assignment: 02/12/2021

Date Inspected: 13/12/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Mah Lian Motor Vehicle Repairer (HQ)
 NO. 38 DEFU LANE 9
 Singapore 539278

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SYNTHETIC BUMPER	Cracked	2,646.61 F	*2,646.61 FL
2	1		*FRONT BUMPER END PANEL RH	Cracked	36.60 F	*36.60 FL
3	1		*FRONT BUMPER COVER RH	Cracked	107.82 F	*107.82 FL
4	1		*FRONT BUMPER SUPPORT SHORT RH	Not Necessary	150.68 F	*- FL
5	1		*FRONT BUMPER COVERING HINGE RH	Not Necessary	12.53 F	*- FL
6	1		*FRONT BUMPER COVERING RH	Not Necessary	12.53 F	*- FL
7	1		*FRONT BUMPER TRIM OUTER RH	Torn	44.16 F	*44.16 FL
8	1		*HEADLAMP RH	Not Necessary	1,057.24 F	*- FL
9	1		*FRONT BUMPER UNDERRIDE PROTECTION ASSY	Cracked	3,671.64 F	*3,671.64 FL
10	1		*STEPWELL LOWER RH	Bent	495.04 F	*495.04 FL
11	1		*STEPWELL SILVER METALIC RH	Damaged	175.53 F	*175.53 FL
12	1		*STEPWELL COVER RH	Missing	5.80 F	*5.80 FL
13	1		*ENTRY MUDGUARD RH	Cracked	962.57 F	*962.57 FL
14	1		*ENTRY MUDGUARD FLASHER RH	Broken	130.00 F	*130.00 FL
15	1		*STEP UNDER SILVER METALIC RH	Not Necessary	115.28 F	*- FL
16	1		*STEP CENTER SILVER METALIC RH	Not Necessary	208.94 F	*- FL
17	1		*ENTRY MUDGUARD COVER RH	Not Necessary	7.65 F	*- FL
18	1		*ENTRY MUDGUARD BRACKET ASSY RH	Repair	259.74 F	*- FL
19	1		*FRONT MUDGUARD INNER RH	Repair	322.19 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	10,422.55	8,275.77
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	827.58
Total Parts (\$)	10,422.55	7,448.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT HEADLAMP & CHECK ALL WIRING & REFOCUS	New	120.00	30.00
2	LABOUR CHARGE TO DISMANTLE & WELD & KNOCK & CUT & REFIT ALL ABOVE PARTS	New	1,800.00	900.00
3	TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA	New	1,200.00	650.00
4	TO RUST PROOFING AT AFFECTED AREA	New	580.00	0.00
Gross Labour Cost (\$\$)			3,700.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >