

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012248/APA3Q2**Date:** 08/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210081588
Claimant Vehicle No :	GBF8827Z	Insured Vehicle No :	GBF9421D
Date of Loss:	30/11/2021	Nature of Claim:	TP
		Claim No:	3497508118SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF8827Z	Engine No:	1KD2672271
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y60K207287
Reg. Date:	31/03/2017 (Man. Year: 2016)	Odometer:	138036 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,685.00	1,111.90	573.10	34.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,090.00	760.00	330.00	30.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,775.00	1,871.90	903.10	32.54
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	2,775.00	1,500.00	1,275.00	45.95
+ GST 7.00/7.00% (S\$)	194.25	105.00	89.25	45.95
Nett Amount (S\$)	2,969.25	1,605.00	1,364.25	45.95
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
(S\$)		2,205.00		
Liabe Amount (50.00%) (S\$)		1,102.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,109.95		
Global Sum Settlement (S\$)		1,100.00		

INSPECTION

Date of Assignment:	02/12/2021	Ryder Auto Pte Ltd (HQ)
Date Inspected:	02/12/2021 Inspected At:	2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417921

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	720.00 FL	*589.00 FL
2	2		*FRONT O/S BUMPER BRACKET	Not Necessary	113.40 FL	*- FL
3	1		*FRONT O/S HEAD-LAMP	Cut	720.20 FL	*720.20 FL
4	1		*FRONT O/S HEAD-LAMP LOWER SEAL	Not Necessary	30.00 FL	*- FL
5	1		*FRONT O/S DOOR COMPANY STICKER	Necessary	30.00 FS	*30.00 FS
6	1		*FRONT O/S DOOR COMPANY STICKER	Necessary	200.00 FS	*100.00 FS
7	1		*FRONT O/S DOOR STEP	Not Necessary	356.40 FL	*- FL
					Sub Total (\$)	2,170.00 1,439.20
					- List Item Discount on L Items 25.00/25.00% (\$)	485.00 327.30
					Total Parts (\$)	1,685.00 1,111.90

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE REAR PORTION ,STRAIGHTEN ,CUTTING & WELDING	New	500.00	300.00
2	TO SPRAY PAINTING	New	500.00	400.00
3	TO CHECK WIRING	New	60.00	30.00
4	TO RE-SEAL ANTI-RUST	New	30.00	30.00
Gross Labour Cost (\$\$)			1,090.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >