5/17/22, 8:18 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21012249/VPA3Q2

17/05/2022 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700075843-04

**Claimant Vehicle** SHC2787P Insured Vehicle No: SLT9433C

No:

Date of Loss: 01/12/2021 Nature of Claim: TP Claim No: 6650683027SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SHC2787P** 

Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) G4LEKU400827 Engine No:

Reg. Date: 30/11/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU187607

Colour: Odometer: 233138 km Blue

**Engine Capacity:** 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 5 mm West Lake 5 mm Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,441.96	758.60	683.36	47.39
Miscellaneous Items		0.00	0.00	0.00	
Labour		760.00	620.00	140.00	18.42
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	2,201.96	1,378.60	823.36	37.39
	+ GST 7.00/7.00% (S\$)	154.14	96.50	57.64	37.39
	Nett Amount (S\$)	2,356.10	1,475.10	881.00	37.39
	+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
	+ Car Rental (2.0 x S	\$129.47/day) (S\$)	258.94		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	1,836.04		
	Global Sui	m Settlement (S\$)	1,800.00		

**INSPECTION** 

Date of Assignment: 02/12/2021

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 02/12/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

**CHEW HSIAO TONG** Adjuster: Thevan Thomas Karthikesavan Manager:

## **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	459.40 FL	*- FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Scratched	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL
5	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 FS	*100.00 FS
6	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 FS	*100.00 FS
7	1		*REAR BUMPER REVERSE SENSOR	Cut	180.00 FS	*180.00 FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	1,707.45	853.25
			- List Item Discount on L Items 20	0.00/20.00% (S\$)	265.49	94.65
				Total Parts (S\$)	1,441.96	758.60
			Report was unsubmitted during this prin	it-out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	20.00
		Gross Labour Cost (S\$)	760.00	620.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >