

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012263/AQCE2

Date: 08/12/2021

REFERENCE

Insured/Claimant:	CHIEW KIA MENG AARON	Policy No:	7210035096	
Date of Loss:	16/11/2021	Nature of Claim:	OD	Claim No: 0727543349SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC7276D		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK058482
Reg. Date:	18/04/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF49JA144473
Colour:	Blue	Odometer:	34230 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$102,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,369.00	8,716.00	15,653.00	64.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,732.00	7,492.00	16,240.00	68.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	48,101.00	16,208.00	31,893.00	66.30
+ GST 7.00/7.00% (S\$)	3,367.07	1,134.56	2,232.51	66.30
Nett Amount (S\$)	51,468.07	17,342.56	34,125.51	66.30

INSPECTION

Date of Assignment:	03/12/2021		
Date Inspected:	01/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,469.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Distorted	3,192.00 FS	*3,192.00 FS
2	1		*FRONT DOOR OUTER SEAL - LH	Necessary	205.00 FS	*205.00 FS
3	1		*BONDING AGENT	* Check	49.00 FS	*- FS
4	1		*CLEANING SOLUTION	* Check	68.00 FS	*- FS
5	1		*APPLICATOR	* Check	8.00 FS	*- FS
6	1		*BUNGS	Not Necessary	4.00 FS	*- FS
7	1		*FRONT DOOR ATTACHEMENT PARTS (NPA)	Not Necessary	0.00 FS	*- FS
8	1		*FRONT DOOR CATCH - LH	* Check	105.00 FS	*- FS
9	1		*REAR DOOR HANDLE TRIM PLATE - LH	Not Necessary	88.00 FS	*- FS
10	1		*REAR DOOR HANDLE HOUSING - LH	Not Necessary	8.00 FS	*- FS
11	1		*FRONT WINDOW - LH	Not Necessary	282.00 FS	*- FS
12	1		*FRONT WINDOW WITH MOTOR - LH	* Check	313.00 FS	*- FS
13	1		*FRONT DOOR CONTROL UNIT - LH	Not Necessary	751.00 FS	*- FS
14	1		*REAR DOOR MOUNTING BAR - LH	Not Necessary	164.00 FS	*- FS
15	1		*REAR DOOR TRIM - LH	Not Necessary	2,054.00 FS	*- FS
16	1		*REAR DOOR - LH	Dented	3,192.00 FS	*3,192.00 FS
17	1		*REAR DOOR OUTER SEAL - LH	Necessary	205.00 FS	*205.00 FS
18	1		*BONDING AGENT	* Check	49.00 FS	*- FS
19	1		*CLEANING SOLUTION	* Check	68.00 FS	*- FS
20	1		*APPLICATOR	* Check	8.00 FS	*- FS
21	1		*REAR WINDOW SEALING STRIP	Not Necessary	17.00 FS	*- FS
22	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	860.00 FS	*- FS
23	1		*REAR DOOR CATCH - LH	* Check	120.00 FS	*- FS
24	2		*REAR DOOR HINGE HALF UPPER PART - LH	* Check	89.00 FS	*- FS
25	2		*REAR DOOR HINGE HALVES LOWER - LH	* Check	92.00 FS	*- FS
26	1		*REAR DOOR SEAL INNER - LH	Not Necessary	222.00 FS	*- FS
27	1		*REAR DOOR TRIM PANEL WIRE HARNESS	Not Necessary	297.00 FS	*- FS
28	1		*REAR WINDOW - LH	Not Necessary	282.00 FS	*- FS
29	1		*REAR WINDOW WITH MOTOR - LH	Not Necessary	338.00 FS	*- FS
30	1		*AIRBAG / CHILD SEAT STICKER	Not Necessary	24.00 FS	*- FS
31	1		*B-PILLAR - LH	Not Necessary	4,052.00 FS	*- FS
32	1		*REAR WINDSCREEN - LH	Not Necessary	1,154.00 FS	*- FS
33	1		*QUARTER WINDOW - LH	Not Necessary	616.00 FS	*- FS
34	2		*PRIMER	Not Necessary	40.00 FS	*- FS
35	1		*DOOR SILL PANEL - LH	Not Necessary	120.00 FS	*- FS
36	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	240.00 FS	*- FS
37	1		*REAR BUMPER	Repair	2,181.00 FS	*- FS
38	1		*REAR BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
39	1		*REAR BUMPER GUIDE SECTION UPPER - LH	Not Necessary	44.00 FS	*- FS
40	2		*REAR BUMPER GUIDE SECTION LOWER - LH / RH	Not Necessary	46.00 FS	*- FS
41	1		*ALUMINIUM RIM	Cut	1,142.00 FS	*1,142.00 FS
42	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
43	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
44	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
45	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
46	1		*METAL FILER POWDER	Necessary	280.00 FS	*280.00 FS
47	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
48	1		*SUNDRIES	* Check	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 24,369.00 8,716.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	0.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS SIDE 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS	New	200.00	150.00
5	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER	New	800.00	0.00
6	TO PUT ON THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	0.00
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
8	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICE. INSPECT FOR DAMAGES	New	700.00	560.00
9	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR AND LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. TO REPAIR LHS B-PILLAR AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,000.00	2,500.00
10	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, DOOR HINGES, DOOR HANDLE, LHS SILL PANEL, LHS B-PILLAR, DRAIN CHANNEL, ROOF CHANNEL, DOOR ENTRANCE AND REAR END PANELLING	New	8,000.00	2,750.00
11	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
13	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	700.00
Gross Labour Cost (\$\$)			23,732.00	7,492.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >