


ASS. FEE: REF: CS EGI 21012265 D913 COB May 2028 2008, May

Front: Date: Estimate Cost: OD / F / F / TP RES / OD RES / EVA / RV / MV To Inspect Vehicle No: at Work in m/s of Insured Policy # Claim # LPMCG7002308 Sum Insured Excess: (Check second) Make Color:

(Police Condition) Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: IDAC Accident Report Consistent? : Yes or No GIA / PR Seen Consistent? : Yes or No Est. Repair: 5 days Res.: Yes or No Limit Sum: 20 % 3 Val: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT



ASSIGNMENT SLP 5255 Y VEH No: Mazda Yr Regn: 2008, May Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: Mazda 5 CO 1999 Colour: Blue A/C: Insured / Std / RE / NA Sp. Reading: 253425 T/Radio: Insured / Std / RE / NA Eng/No: LF10535106 C/Nr: JM6CR10F280304483 Gen. Cond: Good / Fair / Poor / Burnt Steering: In order / Jammed / Leaked / Burnt or Brake: In order / Jammed / Leaked / Burnt or Mod: M / S / R / STD A/Rim or Tyre Size: F: 205/60 R16 R: 11 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUBARU TOYO / YOKO or Pirella Front Rear R/Bal: S mm R/Bal: S mm L/Bal: S mm L/Bal: S mm D.O.A: 02/12/2021 D.O.I: 03/12/2021 Survey held at IDAC Pyc ubi Des. of Damages: Fnt / Rear / O/S / N/S / W/C / Rooftop or Rear The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Brgo TH 8849X
	MV 55K
	LTA 24.1K
	HL 30.9K
	Bryan finalized 16 @ 4500, 5 days. Ored @ 12859.80, 74%

Date/Time, File Pass to? 21/2 14:14:14 : Preli. Report : Final Report Days Of Repair: 5 Resurvey No. of Trip: 2 Survey Feet: Transportation: S + RS: 2 Add Fee: Site Insp (\$) Interview (\$)




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
 Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 211221

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 21.11.2021

Lua Kim Heng

Blk 17 Marsiling Lane #14-229,
Singapore 730017.

Estimate Repair Cost for Vehicle Reg. No: SLP5255Y

1 Pc. Rear Boot <i>Double / grade</i>		1,390.00 ✓
2 Pcs. Rear Boot Absorber <i>HW</i>	@ 199.60	399.20 X
1 Pc. Rear Boot Mazda 5 Emblem <i>HW</i>		85.00 ✓ 61.00
1 Pc. Rear Boot Logo <i>HW</i>		92.00 ✓ 65.00
1 Pc. Rear Boot Handle <i>HW</i>		498.00 X
1 Pc. Rear Boot Wiper Motor <i>1st / Down</i>		465.00 ✓ 428.60
1 Pc. Rear Boot Wiper Arm <i>CRACK</i>		210.00 ✓ 87.10
1 Pc. Rear Boot Inner Garnish <i>CRACK</i>		599.80 ✓ 498.20
10 Pcs. Rear Boot Inner Garnish Clips <i>HW</i>	@ 6.00	60.00 ✓ 15/- SH
2 Pcs. Rear Lamp RH/LH Assy. <i>CRACK</i> <i>0/5 50% SH</i>	@ 689.00	1,378.00 ✓ 689.00 H/S 0/5
4 Pcs. Rear Lamp Holder RH/LH <i>HW</i>	@ 89.00	356.00 X
1 Pc. Rear Bumper <i>distorted</i> <i>50% SH</i>		699.00 ✓ 349.50 SH
2 Pcs. Rear Bumper Reflector <i>HW</i>	@ 178.00	356.00 X
2 Pcs. Rear Bumper Lower Lip <i>HW</i>	@ 140.00	280.00 X
2 Pcs. Rear Bumper Retainer <i>SH</i>	@ 210.00	420.00 X
1 Pc. Rear Bumper Reinforcement <i>HF</i>		398.00 X
2 Pcs. Rear Bumper Bracket <i>HW</i>	@ 198.00	396.00 X
1 Pc. Rear Bumper Inner Garnish <i>SH</i>		299.80 X
10 Pcs. Rear Bumper Clips <i>HW</i>	@ 6.00	60.00 ✓ 15/- SH
1 Set. Rear Bumper Parking Sensor <i>Down</i>		380.00 220/- SH
1 Pc. Rear Windscreen <i>CRACK</i>		1,480.00 ✓ 787.00
1 Pc. Rear Windscreen Moulding <i>HW</i>		298.00 ✓ 72.80
1 Pc. Rear Windscreen Inner Seal <i>HW</i>		90.00 ✓ 42.00
1 Pc. Rear RH Fender <i>HW</i>		1,990.00 X
1 Pc. Rear RH Fender Glass Moulding <i>HW</i>		280.00 X
1 Pc. Rear RH Fender Glass Inner Seal <i>HW</i>		80.00 X
1 Pc. Rear End Panel <i>repl</i>		959.00 X
Total (Panels / Parts):		<u>13,039.80 (SGD)</u>

List 4120.70
20% 3296.56

SH 944.00




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4585 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit rear windscreen, fender glass on all Affected area.	280.00 120/-
To check wiring, remove & refit all wiring for all Accident affected area.	300.00 30/-
To welding, knocking, straightening, repair & renew All accident damage affected area.	1,300.00 600/-
To respray painting on inside, outside panel & all Accident affected area.	1,300.00 600/-
To remove & refit, renew exhaust system.	280.00 1410.00 44
To remove & refit interior garnish trim board, cushion & all affected area.	380.00 44
To rust proof all accident affected area.	200.00 40/-
To wash interior & vacuum cleaning	280.00 84/- 20/-

Total (Labor Charges): 4,320.00 (SGD)

5650.56

4/s 4,500/-

03/12/2021 @ 1315hrs

Not Authorised

L/sun 5 days.

Ryan

LKK Auto


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ALFRED AUTO


Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538

Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E

Email: alfredauto@hotmail.com

Tyre &
Sports Rim



TOTAL COST SUMMARY

PANELS / PARTS	13,039.80
LABOR CHARGES	4,320.00

Grand Total:	<u>17,359.80 (SGD)</u>
--------------	-------------------------------

We shall be glad if you can forward the payment at your early convenience.

**For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E**

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.