

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012267/AQY3N2**Date:** 03/03/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00070012106		
<b>Claimant Vehicle No :</b>	SNC9395U	<b>Insured Vehicle No :</b>	SKB4779U		
Date of Loss:	30/11/2021	Nature of Claim:	TP	Claim No:	SNM21D206964/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNC9395U</b>		Engine No:	A25AN363237
Make & Model:	TOYOTA LEXUS, 2.5 ES300H 4DR SEDAN (AUTO) EXECUTIVE (A)		Chassis No:	JTHB21B1502156455
Reg. Date:	26/11/2021 (Man. Year: 2021)		Odometer:	288 km
Colour:	Silver		Engine Capacity:	2487 cc
Market Value/New Car Price:	N/A		Sum Insured (S\$):	<b>Market Value/New Car Price</b>

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,235.90	2,036.40	2,199.50	51.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,745.00	710.00	2,035.00	74.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,980.90</b>	<b>2,746.40</b>	<b>4,234.50</b>	<b>60.66</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>488.66</b>	<b>192.25</b>	<b>296.41</b>	<b>60.66</b>
<b>Nett Amount (S\$)</b>	<b>7,469.56</b>	<b>2,938.65</b>	<b>4,530.91</b>	<b>60.66</b>

INSPECTION

Date of Assignment:	07/12/2021	Inspected At:	8 Kaki Bukit Ave 4 #08-45/46 Premier@Kaki Bukit Repairer: SK Automobile Pte Ltd
Date Inspected:	03/12/2021	Estimated Period of Repair:	3.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2022)

**Parts:** 143 TOYOTA LEXUS 2.5 ES300H 4DR SEDAN (AUTO) EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SNC9395U)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR TAILLAMP LOWER BRACKET LH/RH	Not Necessary	236.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	1,327.00 FL	*1,327.00 FL
3	1		*REAR BUMPER LOWER DIFFUSER ASSY	Cut	677.00 FL	*677.00 FL
4	1		*REAR BUMPER REFLECTOR LH	Not Necessary	60.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	499.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT SIDE COVER LH	Not Necessary	189.00 FL	*- FL
7	1		*REAR BUMPER INNER SPONGE	Not Necessary	125.00 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	270.00 FL	*- FL
9	2		*REAR BUMPER REVERSE SENSOR	Not Necessary	976.00 FL	*- FL
10	4		*REAR BUMPER REVERSE SENSOR HOLDER (STICK ON)	Necessary	104.00 FL	*104.00 FL
11	4		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	88.00 FL	*88.00 FL
12	1		*SET REAR BUMPER RIVET	Necessary	60.00 FS	*30.00 FS
13	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,691.00</b>	<b>2,256.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	455.10	219.60
<b>Total Parts (\$)</b>	<b>4,235.90</b>	<b>2,036.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,000.00	250.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	750.00	250.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	95.00	0.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	0.00
5	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	120.00	60.00
6	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	350.00	150.00
7	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>2,745.00</b>
				<b>710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >